



PEUGEOT 2008

2008 Electrique 136 ch Allure Pack

VIN NO VR3UKZXZMJ917675
Registration Number GH200LB



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	113386 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2021-12-29	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251024092941
Inspection Date / Place	2025-10-24 / BCA NANTES	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Battery Electric Vehicle	Gearbox Type	CVT (constantly varying transmission)
Colour	Red	Engine Size (cc)	
Engine Size		No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Engine Rating CV		Metalic Colour	Yes
Battery Ownership	Purchase	Battery Size	
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Rental Car	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Radio	Alloys wheels	Front fog lamps
Roof rails	Electrically folding wing mirrors	Rear parking sensors	Stability control
Power assisted steering			

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres


Left Rear Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Right Front Tyre Depth	6

Cosmetic Damage


6 Dommages



0 Dommages



Component		Damage	Comments
1	Hood	Bodywork / Dent / Deformation	
2	Door / Front Left	Paint / Stone Chip	
3	Door Handle / Front Right	Paint / Scratch / Line	
4	Door / Back Right	Paint / Scratch / Line	
5	Door / Front Left	Paint / Stone Chip	
6	Door / Back Left	Paint / Chipping	



1. Hood
Bodywork / Dent / Deformation -



2. Door / Front Left
Paint / Stone Chip -



3. Door Handle / Front Right
Paint / Scratch / Line -



4. Door / Back Right
Paint / Scratch / Line -



5. Door / Front Left
Paint / Stone Chip -



6. Door / Back Left
Paint / Chipping -

Mechanical Condition

Levels

Level - Oil	Not available	Coolant Fluid - Condition	✓
Oil - Condition	NA	Coolant Fluid	✓
Brakes Fluid	✓		

Engine

Cross Member	NA	Serpentine Belt	NA
Control Liquid Leak	✓		

Equipments Test

Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	✓
Electric Windows	✓	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA
AC / Heating System	✓	Parking Sensors / Cameras Functioning	✓
Central Locking	✓	Audio Equipment	✓
Navigation System	✓		

Tyres

Presence Anti-Theft Lock Nut	✓
------------------------------	---

Dashboard Lights

ABS Warning Light	✓	Transmission Warning Light	NA
Diesel Particulate Filter Light	NA	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Service Light	!
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	!	Airbag Warning Light	✓
Brake Warning Light	✓	Level - Fuel / Battery	45
Steering Fluid Level	NA		

Hybrid/EV

Charge Port Condition	✓	Charge lead 1 condition /Charge lead 2 condition	✓
-----------------------	---	--	---

Hybrid System Fault ✓

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	NA
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	NA
Transmission	✓	Clutch Functioning	NA
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.