





# status report

Report number: 000000838646-EN968 Off. Mark: HD-SB 449E

reference number: 30932298

## **Vehicle Data**

## Hyundai Kona (OS)(2017->) Edition 30+ Elektro 2WD

Vehicle identification number .: TMAK281HFNJ057642 mileage read: 54793 km

First Registration /

28.04.2025 11:02 74918

construction Year: 03.05.2022 / 2022 Inspection date/place: Angelbachtal

Bodywork: SUV Body type: hatchback fuel: Transmission type: Automatic

GPS sat nav disk: Hard Disk Drive Displacement / power: 0 ccm / 100 kW (136 PS)

Drive type: front-wheel drive Paint:

Type of paint: Pearl Doors / seats: 5/5

Number of keys: 2 Next HU / AU: 2025-05 / 2025-05

cushion type:

Substance

Service book available:

Yes

Interior Color:

Smoking vehicle:

No

Last service km / on the:

- /-

Vehicle roadworthy: Yes Submitted vehicle documents: Registration Certificate

State outside: 2 - Good condition inside: 2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Dark Knight / MIC



Report number: 0000000838646-EN968 www.huesges-gruppe.de page: 1 from 9



Mounted tires			
Tyre / wheel type:	Summer tires	Aluminium original	
2nd axis - Left / states .		/// 7 mm	
2nd axis - right / states .		/// 7 mm	
1st axis - Left / states .		/// 7 mm	
1st axis - right / states .		/// 7 mm	
Traffic Safety:	Roadworthy		

### Series

- Storage bag on front seat backrests
- Airbag front passenger side can be switched off
- Active brake light (ESS)
- Anti-lock braking system (ABS)
- Audio system: Radio RDS
- Exterior mirror painted
- Roof rails
- Digital Cockpit (Instrumentenanzeige Digital)
- Automatic switch-on for driving lights / light sensor
- Elektromotor 100 kW (cont. 26 kW)
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Driver assistance system: Driving profile selection (Drive Mode)
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Driving assistance system: lane departure warning system (LDWS, Lane Departure Warning System)
- Electric window lift at the front
- Handsfree Bluetooth
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Getriebe für Elektrofahrzeug
- Pretensioners
- Isofix seats for child seat

- Airbag passenger side
- Airbag driver side
- Alarm system
- Drive type: front-wheel drive
- Outside mirror electr. adjustable and heated, both
- Brake Assist
- Roof spoiler
- Rear Parking Sensors
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driver assistance system: hill start assist
- Fahrassistenz-System: Insassenalarm (ROA)
- Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)
- Electric window rear
- Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik
- Windscreen with band filter on top
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Cup holder in front
- Rear window heatable
- Body: 5-door



- Climate
- Headrests adjustable at the back
- Charging cable with Type 2 plug
- Lumbar support seat front left, electr. adjustable
- Steering wheel with multifunction
- Steering column (steering wheel) height adjustable
- Reading light
- Center armrest front with compartment
- Navigations-Paket
- Parking brake electric (EPB)
- Radstand 2600 mm
- Tire pressure monitoring system
- Rear seat back divided / foldable
- Shift / selector lever handle leather
- Side airbag in front
- Seatbelts height adjustable
- Seat cover / upholstery: fabric
- Smartphone Schnittstelle (Apple CarPlay & Android Auto)
- Sun visors with mirror (illuminated)
- Start / Stop system
- Touchscreen-Farbdisplay (8,0 Zoll)
- Türgriffe innen silber
- Glazed tinted
- Seat belt warning system, driver / passenger side
- Heat pump for heating/air conditioning
- Central locking with remote control

- Head airbag system
- Kühlergrill Wagenfarbe
- Ladevorrichtung On-Board-Lader (3-Phasen)
- Steering wheel (leather) with multifunction
- Steering wheel with paddle shifters
- Steering column (steering wheel) longitudinally adjustable
- LM rims
- Facelift
- Notladekabel (ICCB)
- Radio reception digital (DAB +)
- Tire repair kit
- Backup camera
- Schalt-/Wählhebel (Shift by Wire)
- Window fogging detection / control
- Power steering
- Seat front left height adjustable
- Smart kev
- Sonderlackierung Dive in Jeju Uni
- Start-stop button
- Daytime running light LED
- Door handles outside body color
- USB port + AUX-IN port
- Verglasung hinten abgedunkelt (Privacy Glass)
- Immobilizer (electronic)
- Wärmeschutzverglasung

## Special Features

• Mica finish / mineral effect finish

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General exam	
test drive:	Conducted limited
	Because of the conditions a short test drive could be performed only at a moderate speed.
	As part of the test drive further tests were carried out. The results are documented later in
	the report .

Report number: 0000000838646-EN968 www.huesges-gruppe.de page: 3 from 9



Subfloor Inspection: Not performed

A visit to the underbody of the car was not performed.

Mileage plausible: Not testable

Not testable

reference:

Note Road Safe:

## **Accident claims investigation**

Rep. Predamages / -height gross:

Layers of paint thickness

measurement:

Existing collision damage: Not established

On the vehicle body shell were on visual examination found no existing accident damages

(other than the usual signs of use) .

reference:

### Overview of technical examination

Sunroof / convertible: unavailable Seat heating: In order

Brake system: examined limited Engine running: examined limited

#### Implemented technical examination

**air conditioning:** The air conditioning system could be tested only restricted during the visit .

**lighting system:** The Lichtanlange could be considered limited to the tour date .


Sunroof / convertible: unavailable
Seat heating: In order

brake system: The braking system has been tested by a visual inspection.

engine running: Checking the engine running was limited. Here no audible or visual abnormalities were noted.

reference:

### **Damage**



Component Damage Rep kind

1. Rim front - left Deep scratch Smart repair

2. Hood Deep scratch Paint

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear, as in normal use are inevitable (small bumps, dents, scratches).

Report number: 0000000838646-EN968 www.huesges-gruppe.de page: 4 from 9



There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .

Report number: 000000838646-EN968 www.huesges-gruppe.de page: 5 from 9



## Photo documentation



front Left



rear Left



trunk



front Right



rear Right



Inside





instrument cluster



center console



Service book / proof




mileage



HD SB 449E

engine compartment









tires



tires



tires



tires



1. Rim front - left

Deep scratch - Smart repair





2. Hood Deep scratch - Paint



2. Hood **Deep scratch - Paint**