





status report

Customer: Allane SE HCBE

Report number: 0000000844477-EN926 Off. Mark: **MR-SK 805E**

reference number: 30952130

Vehicle Data

Hyundai Kona (OS)(2017->) Edition 30+ Elektro 2WD

Vehicle identification number .: TMAK281HFNJ058634 mileage read: 16656 km

First Registration /

26.05.2025 Siemensstr. 6, construction Year: Inspection date/place: 30.05.2022 / 2022

63329 Egelsbach

Bodywork: Cars Body type: hatchback Transmission type: fuel: **Electric Automatic**

GPS sat nav disk: **Hard Disk Drive** Displacement / power: 0 ccm / 100 kW (136 PS)

Drive type: front-wheel drive Paint:

Type of paint: Metallic Doors / seats: 5/5

Number of keys: Next HU / AU: 2027-05 / 2027-05 2

cushion type: Service book available: **Substance** Yes Interior Color: Maintained service book: **Black** Yes

smoking vehicle: Last service km / on the: No 11280 / 2024-07-25

Vehicle roadworthy: Submitted vehicle documents: Yes

State outside: condition inside: 2 - Good 2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Phantom Black / MIC



0000000844477-EN926 www.huesges-gruppe.de page: 1 from 9 Report number:



Mounted tires			
Tyre / wheel type:	Summer tires	Aluminium original	
1st axis - Left / states .	Michelin	215/55/R17/94V 4 mm	
1st axis - right / states .	Michelin	215/55/R17/94V 4 mm	
2nd axis - Left / states .	Michelin	215/55/R17/94V 6 mm	
2nd axis - right / states .	Michelin	215/55/R17/94V 6 mm	
Traffic Safety:	Roadworthy		

Series

- Storage pocket on front seat backrests
- Airbag switched off
- Active brake light (ESS)
- Anti- lock braking system (ABS)
- Audio System Radio RDS
- painted mirrors
- roof rails
- Digital Cockpit (digital instrument display)
- Off switch for driving light / light sensor
- Electric motor 100 kW (cont. 26 kW)
- Driving assistance system: active lane keeping assistant (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
 Driving assistance system: Autonomous emergency braking function including pedestrian detection (FCA-Ped.)
- Driving Assistance System Driving profile selection (Drive Mode)
- Driving assistance system: safety system with automatic emergency call (ERA GLONASS / eCall)
- Driving Assistance System Lane Departure Warning
- Electric windows front
- handsfree Bluetooth
- Counter- steering assist (Vehicle Stability Management , VSM)
- Cargo net in the trunk / cargo area

- Airbag
- Airbag driver
- alarm system
- Drive Front Wheel Drive
- Power side mirrors . adjustable and heated, both
- brake Assist
- roof spoiler
 3rd brake light
- rear Parking Sensors
- Electr . Brakeforce Distribution
- Electron. Stability Control (ESC) with Brake Assist
- Driving assistance system: attention assistant
- Hill Start Assist
- Driver Assistance System: Occupant Alert (ROA)
- Driving assistance system: Lane Following Assist (LFA)
- Electric window . behind
- Electric windows in front, with up/down automatic
- Windscreen with band filter above
- Baggage / cargo area lamp
- Luggage compartment cover / shade

Report number: 0000000844477-EN926 www.huesges-gruppe.de page: 2 from 9



- Cruise control system (cruise control) with distance control ACC
- Cup holders front
- heated rear window
- Body 5-door
- Head airbag system
- Body color grille
- Charging device on-board charger (3-phase)
- Steering wheel (leather) with multifunction
- Steering wheel with paddles
- Steering column (steering wheel) longitudinally adjustable
- LM rims
- Facelift
- Emergency charging cable (ICCB)
- Digital radio reception (DAB+)
- Tire repair kit
- Rear View Camera
- Shift/Selector Lever (Shift by Wire)
- Window fogging detection / control
- power steering
- Front left seat height adjustment
- Smart Key
- Special paint job Dive in Jeju Uni
- Start-stop button
- LED daytime running lights
- Exterior door handles body color
- USB + AUX IN connection
- Glazing behind darkened
- Immobiliser (electronic)
- thermal insulation glazing

- Transmission for electric vehicle
- Belt tensioners
- Isofix admissions for child seat
- Climate Control
- Rear headrests adjustable
- Charging cable with Type 2 plug
- Lumbar support front left seat , electric. adjustable
- Multifunction steering wheel
- Steering column (steering wheel) adjustable in height
- reading Light
- Front center armrest with compartment
- Navigation Package
 Sound-System KRELL, subwoofer, 8 speakers, Lifetime MapCare
 (Internetbasierende Dienste), navigation system, Service system: Remote
 Services (Blue Link), Touchscreen color display (10.25 inch), Driver
 assistance system: traffic sign assistant
- Electric parking brake (EPB)
- Wheelbase 2600mm
- Tire Pressure Monitoring System
- Rear seat backrest split / folding
- Gearshift / selector lever leather
- Front Side Airbags
- Seat belts front height adjustable
- Seat cover / upholstery fabric
- Smartphone interface (Apple CarPlay & Android Auto)
- Sun visors with mirrors (illuminated)
- Start / Stop system
- Touchscreen color display (8.0 inch)
- Door handles inside silver
- tinted glazing
- Seat belt warning system, driver/passenger side
- Heat pump for heating/air conditioning
- Central locking with remote control

Special Features

Mica paint / mineral effect spraying

Report number: 0000000844477-EN926 www.huesges-gruppe.de page: 3 from 9



We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General exam

test drive: Not performed

It was not carried out a test drive of the vehicle during the tour.

Subfloor Inspection: Not performed

A visit to the underbody of the car was not performed.

Mileage plausible: Not testable

Not testable

reference:

Note Road Safe:

Accident claims investigation

Rep. Predamages / -height gross: No detectable

A visual inspection of the outer body skin did not reveal any previous damage.

Layers of paint thickness

Within the tolerances

measurement:

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin.

The measured values were within the tolerances of original finishes. Evidence that points to

a repaired accident damage or repainting carried out, were identified.

Existing collision damage: Not established

On the vehicle body shell were on visual examination found no existing accident damages

(other than the usual signs of use).

reference:

Overview of technical examination

Air conditioning: Examined limited Seat heating: Examined limited

Lighting system: examined limited Sunroof / convertible: unavailable

Brake system: examined limited Engine running: not possible

examined limited Figure running: not possible

Implemented technical examination

air conditioning: The air conditioning system could be tested only restricted during the visit .

Seat heating: Examined limited

lighting system: The Lichtanlange could be considered limited to the tour date.

Sunroof / convertible: unavailable

brake system: The braking system has been tested by a visual inspection .

engine running: A field test of the engine could not be performed

reference: *

Report number: 0000000844477-EN926 www.huesges-gruppe.de page: 4 from 9



A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear, as in normal use are inevitable (small bumps, dents, scratches).

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects.

Report number: 0000000844477-EN926 www.huesges-gruppe.de page: 5 from 9



Photo documentation



front Left



rear Right



trunk





rear Left



Inside





instrument cluster



center console



Service book / proof



mileage




key



Service book / proof






Service book / proof



engine compartment



tires



Others




rims



tires







0000000844477-EN926 www.huesges-gruppe.de page: 9 from 9 Report number: