



CITROEN C3 ENTREPRISE

C3 SOCIETE PURE TECH 82 S&S FEEL

BUSINESS R

VIN NO VF7SXHMRPKT568517
Registration Number FH063XH



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	0	2	135881 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2019-07-16	France

Inspection Report Summary

Customer	BCAuto Encheres	Mechanical Grade	
Inspection Date / Place	2025-12-15 / BCA HOUECOURT	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1199
Engine Size	1.2	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Charging Cables		No of Seats	5
NEDC CO2 Rating (g/km)	96	Seat Covering	
Engine Rating CV	4	Metalic Colour	
First Registration / Construction Year	2019-07-16 / 1900-01-01	Arrival Date	2025-12-12


Vehicle History & Documents

Service Book Available	Present	Previous Usage	Normal Use
Manufacturer Warrenty		Odometer Warranty	No
Next Service Mileage	km		

Vehicle Remarketing Imagery

[Click Here For Larger Images](#)





Equipment

Central locking	Cruise control	Radio	Power assisted steering
-----------------	----------------	-------	-------------------------

Equipment Details


Air Conditioning	No	Seat Heating	No
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres


Left Rear Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Right Front Tyre Depth	5
Tyres Comment	Acceptable		

Cosmetic Damage

4 Dommages



5 Dommages



Component	Damage	Comments
1 Floor Carpet	Interior / Dirty	
2 Panel Filling / Front Left	Interior / Stained	
3 Floor Carpet	Interior / Dirty	
4 Tailgate Upholstery / Back	Interior / Dirty	
5 Trunk Carpet	Interior / Dirty	
6 Hubcap / Front Right	Out of Bodywork / Scratch	
7 Mirror Shell / Front Right	Paint / Scratch / Line	
8 Mirror Shell / Front Left	Paint / Scratch / Line	
9 Tailgate	Paint / Scratch / Line	



1. Floor Carpet
Interior / Dirty -



2. Panel Filling / Front Left
Interior / Stained -



3. Floor Carpet
Interior / Dirty -



4. Tailgate Upholstery / Back
Interior / Dirty -



5. Trunk Carpet
Interior / Dirty -




6. Hubcap / Front Right
Out of Bodywork / Scratch -



7. Mirror Shell / Front Right
Paint / Scratch / Line -



8. Mirror Shell / Front Left
Paint / Scratch / Line -



9. Tailgate
Paint / Scratch / Line -

Mechanical Condition

Levels

Oil level	✓	Level - Oil	✓
Coolant Fluid - Condition	✓	Coolant Fluid	✓
Brakes Fluid	✓		

Equipments Test

Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	NA
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	Dump / Trail / Tail Gate Lift	NA
Electric Windows	✓	Audio Equipment	✓
Navigation System	NA	AC / Heating System	!
Central Locking	✓		

Engine

Cross Member	✓	Serpentine Belt	!
Control Liquid Leak	✓		

Comments

Comments	Entretien depasser
----------	--------------------

Dashboard Lights

ABS Warning Light	✓	Transmission Warning Light	✓
Diesel Particulate Filter Light	✓	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Service Light	✓
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Steering Fluid Level	NA
Level - Fuel / Battery	25		

Hybrid/EV

Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
-----------------------	----	--	----

Test Drive Inspection

Test Drive

Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	✓
Transmission	✓	Clutch Functioning	✓
Brakes Functionning	!	Steering	✓

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

! *Damages or malfunction detected that requires repairs by the buyer*

NA *Not applicable*

— *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.