

# HYUNDAI KONA Kona Electrique 64 kWh - 204 ch Creative



VIN NO TMAK381GFNJ056394 Registration Number GF425TS

MOT Date

★-

Last Service

**=**-

**Number of Owners** 

**:2:**-

Last Service Mileage

**2** 

Number of Keys

**P**1

First Registration Date

2022-04-12

**Odometer Reading** 

**2** 39234 km

Country First Registered

#### **Inspection Report Summary**

Customer	BCAuto Encheres	Report Number	P20250919104319
Inspection Date / Place	2025-09-19 / BCA AUNAY	Cosmetic Grade	3

#### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Battery Electric Vehicle	Gearbox Type	CVT (constantly varying transmission)
Colour	Blue	Engine Size (cc)	
Engine Size		No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Battery State of Health	97		

## Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			
































# Equipment

Central locking	Radio	Alloys wheels	Cruise control
Power assisted steering	Satellite navigation	Electrically folding wing mirrors	Rear parking sensors
Stability control	Front fog lamps	Roof rails	


## **Equipment Details**

Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

## Wheels & Tyres

Left Rear Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Right Front Tyre Depth	4

## Cosmetic Damage



Component	Damage	Comments
1 Mud Flap / Back Left	Paint / Chipping	
2 Corner Bumper / Front Right	Bodywork / Breakage	
3 Bumper / Front	Paint / Chipping	



1. Mud Flap / Back Left Paint / Chipping -

2. Corner Bumper / Front Right Bodywork / Breakage -



3. Bumper / Front Paint / Chipping -

## **Mechanical Condition**

Levels			
Coolant Fluid - Condition	•	Oil - Condition	NA
Level - Oil	•	Brakes Fluid	•
Coolant Fluid	•		
Tyres			
Presence Anti-Theft Lock Nut	•		
Dashboard Lights			
ABS Warning Light	•	Diesel Particulate Filter Light	•
ESP Fault/Traction Control Malfunction Light	•	4WD Light	•
Dashboard Working	•	Engine Light	•
Oil Pressure Warning Light	•	Airbag Warning Light	•
Brake Warning Light	•	Level - Fuel / Battery	26
Transmission Warning Light	•	Service Light	•
Steering Fluid Level	•		
Equipments Test			
Electric Windows	•	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA
Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	•
Central Locking	•	Audio Equipment	<b>©</b>
Navigation System	•	AC / Heating System	•
Parking Sensors / Cameras Functioning	•		
Hybrid/EV			
Charge Port Condition	•	Charge lead 1 condition /Charge lead 2 condition	•
Hybrid System Fault	•		
Engine			
Cross Member	•	Serpentine Belt	•

Control Liquid Leak

#### **Test Drive Inspection**

Test Drive			
Engine functioning	<b>②</b>	Engine / Aux Belt / Pulley Noise	•
Vehicle Starts	•	Steering Noise/Gripping	•
Engine Power	•	Smoke Quantity	NA
Transmission	•	Clutch Functioning	NA
Steering	<b>⊘</b>	Brakes Functionning	<b>Ø</b>
<ul> <li>No troubles detected, good condition or correct tests, according to vehicle age and mileage</li> <li>Damages or malfunction detected that requires repairs by the buyer</li> <li>Not applicable</li> <li>Not tested</li> </ul>			

#### **Disclaimer Section**

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.