

HYUNDAI KONA Kona Electrique 39 kWh - 136 ch Intuitive



VIN NO TMAK281HFNJ054814 Registration Number GF836QB

MOT Date

Number of Owners

Number of Keys Odor

☆-

::: -

P1

Odometer Reading

▲
Last Service

_

2 43615 km

#

Last Service Mileage

First Registration Date

Country First Registered

23-

2022-04-01

8

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250725071950
Inspection Date / Place	2025-07-28 / BCA	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Battery Electric Vehicle	Gearbox Type	CVT (constantly varying transmission)
Colour	Blue	Engine Size (cc)	
Engine Size		No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Battery State of Health	97		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			

































Equipment

Right Rear Tyre Depth


Central locking	Rear parking sensors	Stability control	Front fog lamps
Radio	Alloys wheels	Cruise control	Power assisted steering
Favinment Dataile			
Equipment Details			
Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		
Wheels & Tyres			
Left Rear Tyre Depth	5	Left Front Tyre Depth	5

Right Front Tyre Depth

5

5

Cosmetic Damage



	Component	Damage	Comments
1	Steering Wheel / Front	Interior / Scratched	
2	Fender / Back Left	Paint / Chipping	
3	Fender / Back Left	Paint / Chipping	
4	Roof Molding / Left	Paint / Poor Previous Repair	



1. Steering Wheel / Front Interior / Scratched -

2. Fender / Back Left Paint / Chipping -



3. Fender / Back Left Paint / Chipping -

4. Roof Molding / Left Paint / Poor Previous Repair -

Mechanical Condition

Levels			
Coolant Fluid - Condition	⊘	Oil - Condition	NA
Level - Oil	Not available	Coolant Fluid	•
Brakes Fluid	•		
Tyres			
Presence Anti-Theft Lock Nut	•		
Dashboard Lights			
ABS Warning Light	•	Diesel Particulate Filter Light	NA
ESP Fault/Traction Control Malfunction Light	⊘	4WD Light	NA
Dashboard Working	•	Engine Light	•
Oil Pressure Warning Light	•	Airbag Warning Light	•
Brake Warning Light	•	Level - Fuel / Battery	50
Transmission Warning Light	•	Service Light	•
Steering Fluid Level	NA		
Equipments Test			
Electric Windows	⊘	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA
Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	•
Central Locking	•	Audio Equipment	•
Navigation System	NA	AC / Heating System	•
Parking Sensors / Cameras Functioning	•		
Hybrid/EV			
Charge Port Condition	⊘	Charge lead 1 condition /Charge lead 2 condition	•
Hybrid System Fault	⊘		
Engine			
Cross Member	NA	Serpentine Belt	•

0 1	11:-	: -1	1 - 1	
Control	I LIQ	ula	Leak	



Test Drive Inspection

Test Drive			
Engine functioning	②	Engine / Aux Belt / Pulley Noise	NA
Vehicle Starts	•	Steering Noise/Gripping	•
Engine Power	NA	Smoke Quantity	NA
Transmission	•	Clutch Functioning	Ø
Steering	⊘	Brakes Functionning	•
	d condition or correct tests, accord letected that requires repairs by th		

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.