



status report

Customer:	Allane SE HCBE	Off. Mark :	GAP-BP 14E
Report number:	0000000804148-EN968		
reference number:	30835462		

Vehicle Data

Hyundai Kona (OS)(2017->) Trend Elektro 2WD

Vehicle identification number .:	KMHK381HFMU132621	mileage read:	8091 km
First Registration /			13.11.2024 13:49 82467
construction Year:	18.11.2021 / 2021	Inspection date/place:	Garmisch-Partenkirchen
Bodywork:	SUV	Body type:	hatchback
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	Hard Disk Drive	Displacement / power:	0 ccm / 100 kW (136 PS)
Drive type:	front-wheel drive	Paint:	Surfy Blue / Phantom Black roo / MET
Type of paint:	Multi-colour painting	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	2026-10 / 2026-10
cushion type:	Substance	Service book available:	Yes
Interior Color:	Gray	Maintained service book:	No
smoking vehicle:	No	Last service km / on the:	7485 / 2024-09-09
Vehicle roadworthy:	Yes	Submitted vehicle documents:	Registration Certificate
State outside:	2 - Good	condition inside:	2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Mounted tires

	Summer tires	Aluminium original
Tyre / wheel type:		
1st axis - Left / states .	Michelin	215/-/R17/-- 6 mm
1st axis - right / states .	Michelin	215/-/R17/-- 6 mm
2nd axis - Left / states .	Michelin	215/-/R17/-- 6 mm
2nd axis - right / states .	Michelin	215/-/R17/-- 6 mm
Traffic Safety:	Roadworthy	

Series

- | | |
|---|--|
| <ul style="list-style-type: none"> • 3rd brake light • Storage bag on front seat backrests • Airbag front passenger side can be switched off • Active brake light (ESS) • Ambient lighting • Drive type: front-wheel drive • Outside mirror electr. anklappbar • Exterior mirror painted • Brake Assist • Roof spoiler • Rear Parking Sensors • Electr. Brake force distribution • Electron. Stability control (ESC) with brake assistant • Fahrassistenz-System: Aufmerksamkeits-Assistent • Driving assistance system: Autonomous emergency braking function including front collision warning (FCA) • Driver assistance system: hill start assist • Driver assistance system: Driving profile selection (Drive Mode) • Fahrassistenz-System: Insassenalarm (ROA) • Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA) • Electric window rear • Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik | <ul style="list-style-type: none"> • 6 Lautsprecher • Airbag passenger side • Airbag driver side • Alarm system • Anti-lock braking system (ABS) • Audio system: Radio RDS • Outside mirror electr. adjustable and heated, both • Indicator LED integrated in the exterior mirror • Roof rails • Digital Cockpit (Instrumentenanzeige Digital) • Automatic switch-on for driving lights / light sensor • Elektromotor 100 kW (cont. 26 kW) • Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System) • Driving assistance system: Autonomous emergency braking function including cyclist detection (FCA-Cyc.) • Driving assistance system: Autonomous emergency braking function including pedestrian detection (FCA-Ped.) • Driving assistance system: parking assistance front and rear • Driver assistance system: high beam assistant • Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall) • Driving assistance system: lane departure warning system (LDWS, Lane Departure Warning System) • Electric window lift at the front • Handsfree Bluetooth |
|---|--|

- | | |
|---|--|
| <ul style="list-style-type: none"> • Windscreen with band filter on top • Countersteering support (Vehicle Stability Management, VSM) • Luggage net in the luggage / loading space • Speed limiter system (speed limiter) • Getriebe für Elektrofahrzeug • Pretensioners • Rear window heatable • Induction charger for smartphone • Isofix seats for child seat • Climate • Headrests adjustable at the back • Charging cable with Type 2 plug • Steering wheel (leather) with multifunction • Steering wheel with multifunction • Steering column (steering wheel) height adjustable • Reading light • LM-Felgen 7x17 • Notladekabel (ICCB) • Radio reception digital (DAB +) • Tires 215/55 R17 ..V • Tire pressure monitoring system • Rear seat back divided / foldable • Shift / selector lever handle leather • Rain-sensing wipers • Side airbag in front • Seatbelts height adjustable • Seat cover / upholstery: fabric • Smart key • Start-stop button • Daytime running light LED • Trend-Paket • Türgriffe innen silber • Glazed tinted • Seat belt warning system, driver / passenger side • Wireless SmartLink (Apple CarPlay) • Wärmeschutzverglasung | <ul style="list-style-type: none"> • Frontscheibe wärmedämmend • Gepäck-/Laderaumleuchte • Luggage compartment cover / roller blind • Cruise control system (tempomat) with distance control ACC • Cup holder in front • Taillights LED • Tweeter • Interior mirror with automatic dimming • Body: 5-door • Head airbag system • Kühlergrill Wagenfarbe • Lumbar support seat front left, electr. adjustable • Lenkrad heizbar • Steering wheel with paddle shifters • Steering column (steering wheel) longitudinally adjustable • Headlamp leveling • Center armrest front with compartment • Parking brake electric (EPB) • Radstand 2600 mm • Tire repair kit • Backup camera • Schalt-/Wählhebel (Shift by Wire) • Window fogging detection / control • Scheinwerfer Voll-LED • Power steering • Seat front left height adjustable • Heated seats in the front • Sun visors with mirror (illuminated) • Start / Stop system • Touchscreen-Farbdisplay (8,0 Zoll) • Door handles outside body color • USB port + AUX-IN port • Verglasung hinten abgedunkelt (Privacy Glass) • Immobilizer (electronic) • Heat pump for heating/air conditioning • Central locking with remote control |
|---|--|

Special Features

- Individual roof painting
- GPS package
Sound-System KRELL, subwoofer, 8 speakers, Lifetime MapCare
(Internetbasierende Dienste), navigation system, Service system: Remote
Services (Blue Link), Touchscreen color display (10.25 inch), Driver
assistance system: traffic sign assistant
- Metallic paint

We remind you that the data provided were taken from the DAT database.
No liability can be assumed for the completeness and correctness.

General exam

test drive:	Conducted limited Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .
Subfloor Inspection:	Not performed A visit to the underbody of the car was not performed .
Mileage plausible:	Not testable Not testable
reference:	
Note Road Safe:	

Accident claims investigation

Rep. Predamages / -height gross:	
Layers of paint thickness measurement:	
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview of technical examination

Brake system:	examined limited	✗	Engine running:	examined limited	✗
----------------------	------------------	---	------------------------	------------------	---

Damage

	Exterior and Styling		
	Component	Damage	Rep kind
1.	Front door - left	Wear and tear	Without repair
2.	Front bumper	Chipping from stones	Paint
	Others		
	Component	Damage	Rep kind

3.	Serviceintervall nicht eingehalten - Wertminderung	Not okay
----	--	----------

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Hüsches Gruppe®
Die Gutachter

Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside




mileage



center console



key



Service book / proof



Others



Others



Others



engine compartment



tires



tires



tires



tires



1. Front door - left
Wear and tear - Without repair



2. Front bumper
Chipping from stones - Paint