

NISSAN LEAF Leaf Electrique 40kWh N-Connecta



VIN NO SJNFAAZE1U0044479 Registration Number FD213CC

MOT Date

Number of Owners

Number of Keys

Odometer Reading

₩-

:2:

P2

131763 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

#-

❷-

= 2019-01-14

8

Inspection Report Summary

| Customer | BCAuto Encheres | Report Number | P20250703114740 |
|-------------------------|------------------|----------------|-----------------|
| Inspection Date / Place | 2025-07-03 / BCA | Cosmetic Grade | 2 |

Vehicle Summary

| Vehicle Condition | Runner | VAT Type | Exempt Rate |
|-------------------|--------------------------|--------------------|---------------------------------------|
| Fuel Type | Battery Electric Vehicle | Gearbox Type | CVT (constantly varying transmission) |
| Colour | White | Engine Size (cc) | |
| Engine Size | | No of Doors | 5 |
| Body Type | Hatchback | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Charging Cables | | WLTP CO2 Emissions | |

Vehicle History & Documents

| Service Book Available | Missing | Next Service Mileage | km |
|------------------------|------------|----------------------|----|
| Previous Usage | Normal Use | Imported | No |
| Manufacturer Warrenty | | | |




































Equipment

| Central locking | Radio | Alloys wheels | Front fog lamps |
|-------------------------|-----------------------------------|----------------------|-----------------|
| Power assisted steering | Electrically folding wing mirrors | Rear parking sensors | Cruise control |
| Front parking sensors | Satellite navigation | | |

Equipment Details

| Seat Heating | Front and Rear | Air Conditioning | Yes |
|------------------------|----------------|-----------------------|-----|
| Wheels & Tyres | | | |
| Left Rear Tyre Depth | 7 | Left Front Tyre Depth | 5 |
| Right Front Tyre Depth | 3 | Right Rear Tyre Depth | 6 |

Cosmetic Damage



| 14 | Corner Bumper / Back Right | Paint / Scratch / Line |
|----|-----------------------------|------------------------|
| 15 | Rocker Panel / Center Right | Paint / Scratch / Line |



1. Door Handle / Front Left Bodywork / Assembly -

2. Seat Cushion / Front Left Interior / Stained -



3. Seat Cushion / Front Right Interior / Stained -

4. Seat / Back Right Interior / Stained -



5. Mirror Shell / Front Right Paint / Scratch / Line -

6. Rim / Front Right
Out of Bodywork / Scratch -



7. Corner Bumper / Front Right Paint / Chipping -

8. Corner Bumper / Front Left Paint / Chipping -



9. Mirror Shell / Front Left Paint / Scratch / Line -

10. Door / Front Left Paint / Chipping -



11. Door / Back Left Paint / Chipping -


12. Rim / Back Left Out of Bodywork / Scratch -



13. Tailgate Paint / Scratch / Line -



14. Corner Bumper / Back Right Paint / Scratch / Line -



15. Rocker Panel / Center Right Paint / Scratch / Line -

Mechanical Condition

| Levels | | | |
|---------------------------------|---------------|---|----|
| Level - Oil | Not available | Coolant Fluid - Condition | • |
| Oil - Condition | NA | Coolant Fluid | • |
| Brakes Fluid | • | | |
| Engine | | | |
| Cross Member | • | Serpentine Belt | NA |
| Control Liquid Leak | • | | |
| Equipments Test | | | |
| Dump / Trail / Tail Gate Lift | NA | Main & Spare Keys Functioning | • |
| Electric Windows | ⊘ | Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test | NA |
| AC / Heating System | • | Parking Sensors / Cameras Functioning | • |
| Central Locking | ⊘ | Audio Equipment | • |
| Navigation System | • | | |
| Tyres | | | |
| Presence Anti-Theft Lock Nut | ⊘ | | |
| Dashboard Lights | | | |
| ABS Warning Light | ② | Transmission Warning Light | • |
| Diesel Particulate Filter Light | NA | ESP Fault/Traction Control Malfunction Light | • |
| 4WD Light | NA | Service Light | • |
| Dashboard Working | ⊘ | Engine Light | • |
| Oil Pressure Warning Light | ⊘ | Airbag Warning Light | • |
| Brake Warning Light | • | Level - Fuel / Battery | 20 |
| Steering Fluid Level | NA | | |
| Hybrid/EV | | | |
| Charge Port Condition | • | Charge lead 1 condition /Charge lead 2 condition | • |

| Hybrid | System | Fault |
|--------|--------|-------|
|--------|--------|-------|



Test Drive Inspection

| Test Drive | | | |
|---|----------|-------------------------------------|----|
| Engine functioning | • | Engine / Aux Belt / Pulley Noise | NA |
| Steering Noise/Gripping | • | Vehicle Starts | • |
| Engine Power | • | Smoke Quantity | NA |
| Transmission | • | Clutch Functioning | NA |
| Steering | ② | Brakes Functionning | • |
| No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer Not applicable Not tested | | | |

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.