



HYUNDAI KONA

Kona Electrique 39 kWh - 136 ch Intuitive

VIN NO TMAK281HFNJ046040
Registration Number GD756BX



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	30216 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2021-11-13	-

Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20250721164223
Inspection Date / Place	2025-07-21 / BCA ANGOULEME	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Battery Electric Vehicle	Gearbox Type	CVT (constantly varying transmission)
Colour	Black	Engine Size (cc)	
Engine Size		No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment

Central locking	Radio	Alloys wheels	Cruise control
Electrically folding wing mirrors	Rear parking sensors	Stability control	Power assisted steering


Equipment Details

Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Wheels & Tyres

Left Rear Tyre Depth	5	Left Front Tyre Depth	4
Right Rear Tyre Depth	5	Right Front Tyre Depth	4

Cosmetic Damage




Component		Damage	Comments
1	Hood	Bodywork / Dent / Hail Area	
2	Corner Bumper / Front Left	Paint / Scratch / Line	
3	Door / Front Left	Paint / Scratch / Line	
4	Door / Back Left	Paint / Scratch / Line	
5	Door / Back Left	Paint / Scratch / Line	
6	Corner Bumper / Back Left	Paint / Chipping	
7	Roof	Bodywork / Dent / Hail Area	
8	Door / Front Right	Paint / Scratch / Line	



1. Hood
Bodywork / Dent / Hail Area -



2. Corner Bumper / Front Left
Paint / Scratch / Line -



3. Door / Front Left
Paint / Scratch / Line -




4. Door / Back Left
Paint / Scratch / Line -




5. Door / Back Left
Paint / Scratch / Line -



6. Corner Bumper / Back Left
Paint / Chipping -



7. Roof
Bodywork / Dent / Hail Area -



8. Door / Front Right
Paint / Scratch / Line -

Mechanical Condition

Levels

Coolant Fluid - Condition	NA	Oil - Condition	NA
Level - Oil	Not available	Coolant Fluid	NA
Brakes Fluid	NA		

Engine

Cross Member	✓	Serpentine Belt	✓
Control Liquid Leak	NA		

Tyres

Presence Anti-Theft Lock Nut	✓
------------------------------	---

Dashboard Lights

ABS Warning Light	✓	Diesel Particulate Filter Light	NA
ESP Fault/Traction Control Malfunction Light	✓	4WD Light	NA
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Level - Fuel / Battery	80
Transmission Warning Light	✓	Service Light	✓
Steering Fluid Level	NA		

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	Dump / Trail / Tail Gate Lift	NA
Central Locking	✓	Audio Equipment	✓
Navigation System	✓	AC / Heating System	✓
Parking Sensors / Cameras Functioning	✓		

Hybrid/EV

Charge Port Condition	✓	Charge lead 1 condition / Charge lead 2 condition	✓
-----------------------	---	---	---

Hybrid System Fault ✓

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Vehicle Starts	✓	Steering Noise/Gripping	✓
Engine Power	✓	Smoke Quantity	NA
Transmission	✓	Clutch Functioning	NA
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.