



Inspection Report

Customer	BCA Sweden	Cosmetic Grade	5
Registration Number	WFX28D	Mechanical Grade	A

Vehicle Data

Nissan Leaf Acenta 40 kWh - 2020

Vehicle Identification Number	SJNFAAZE1U0102011	Odometer Reading	75653 km
First Registration / Construction Year	2020-08-27 / 2020-08-01	Inspection Date / Place	2025-05-14 / Strängnäs
Fuel Type	Battery Electric Vehicle	Gearbox Type	Automatic
Colour	White	Number of Keys	2
Service Book Available	Missing	Service History	
Last Service Km / Date	- / -	Arrival Date	2025-05-13

Mounted Tires

Tyre / Wheel Type	Four Seasons
	//R16 / 3 mm
	//R16 / 3 mm
	//R16 / 6 mm
	//R16 / 6 mm

Unmounted Tires

Tyre / Wheel Type	Summer
	//R16 / 1 mm
	//R16 / 1 mm
	//R16 / 1 mm
	//R16 / 1 mm

Equipment

• Heated steering wheel	• Bluetooth
• Cruise control	• Digital Radio
• Rain sensitive windscreen wipers	• Reversing Camera
• Satellite navigation	

Comments Test Drive

Comment

Checklist

Chipped
Testdriven

Stickers

Damage


Component	Damage
1 Service Book	Interior / Missing
2 Door Step / Front Left	Interior / Scratched
3 Windshield / Front	Paint / Chipping
4 Shield / Front	Paint / Scratch / Scuff
5 Färgskillnad på flera paneler, märken efter dekalers/color difference on several panels,marks after stickers	Paint / Poor Previous Repair
6 Rocker Panel / Center Right	Bodywork / Dent / Dent
7 Set of 4 Winter Wheels	Bodywork / Dent / Deformation
8 Pillar / Back Right	Bodywork / Dent / Dent
9 Fender / Back Right	Bodywork / Dent / Dent
10 Shield / Back	Bodywork / Breakage / Crack
11 Tire / Front Left	Tire
12 Tire / Front Right	Tire
13 Tire / Back Left	Tire
14 Tire / Back Right	Tire
15 Pillar / Back Left	Bodywork / Dent / Dent
16 Fender / Back Left	Bodywork / Dent / Dent
17 Door / Back Right	Paint / Scratch / Scuff
18 Door / Front Right	Paint / Scratch / Scuff
19 Rim / Back Left	Out of Bodywork / Scratch
20 Roof Upholstery	Interior / Scratched

Photo Documentation













1. Service Book

Interior / Missing



2. Door Step / Front Left
Interior / Scratched



3. Windshield / Front
Paint / Chipping



4. Shield / Front
Paint / Scratch / Scuff



5. Färgskillnad på flera paneler, märken efter dekaler/color difference on several panels,marks after stickers

Paint / Poor Previous Repair

Färgskillnad på flera paneler, märken efter dekaler/color difference on several panels,marks after stickers



6. Rocker Panel / Center Right

Bodywork / Dent / Dent



7. Set of 4 Winter Wheels

Bodywork / Dent / Deformation

Snedslitna vinterdäck /uneven worn winter tires



8. Pillar / Back Right

Bodywork / Dent / Dent



9. Fender / Back Right

Bodywork / Dent / Dent




10. Shield / Back

Bodywork / Breakage / Crack



11. Tire / Front Left

Tire



12. Tire / Front Right

Tire



13. Tire / Back Left

Tire




14. Tire / Back Right

Tire




15. Pillar / Back Left

Bodywork / Dent / Dent




16. Fender / Back Left

Bodywork / Dent / Dent



17. Door / Back Right

Paint / Scratch / Scuff



18. Door / Front Right

Paint / Scratch / Scuff



19. Rim / Back Left

Out of Bodywork / Scratch



20. Roof Upholstery
Interior / Scratched