




Hyundai KONA EV Fashion 64 kWh, Feb-20, 137,923 km



Initial registration	17-02-2020
Initial Dutch Registration	17-02-2020
European Type Approval	e4*2007/46*1259*06
Mileage reading / hour counter reading	137,923 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	1660 kg
Doors	5
Power capacity	150 kW
Emission code / Energy label	Z
Wheelbase	260
Loading space	
Load capacity	
RDW details	
Battery capacity	64 kWh
Range	484 km
Battery health	99 %
Charging cables type	2
AC/DC	ACDC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Gray
Country of registration	The Netherlands
Indicative catalog price	€42,210

Accessories fitted to vehicles



Rear view camera



Bluetooth telephone connection



Navigation



Adaptive cruise control



Central locking remote control



Parking sensors rear



Apple Carpl./Android Car



Electric windows front + rear



Rain sensor



Audio installation



Alloy rims



Power steering



Automatic air conditioning ECC




Metallic paint



Comments

No remarks







Vehicle state

MOT due date	17-02-2026	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	At Barneveld location	Wheel locks	Not present
					

Technical state			
Group	Observations	Comments	
No information			
Comments			
No remarks			

Tyres			
Rim size	17"		
Wheel	Brand	Type	Tread depth
Front wheel left	Different	Summer tyre	2 mm
Front wheel right	Different	Summer tyre	2 mm
Rear wheel left	Different	Summer tyre	2 mm
Rear wheel right	Different	Summer tyre	2 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection		
Incident	Component	Observations
Acceptable damage		
1	Interior	dog odor
	Exterior	car wash scratches
	Front	stone impact
Unacceptable damage		
2	Interior	missing part, hoedenplank ontbreekt
3	Front seat left	dirt (interior)
4	Rear seat	dirt (interior)
5	Front screen	scratch(es) and/or pit(s)
6	Front bumper	little scratch(es)

7		Wheel rim right-front	scuffed
8		Front door right	little scratch(es)
9		Rear door right	little dent(s)
10		Rear right rim	scuffed
11		Rear bumper	little scratch(es)
12		Rear door left	little scratch(es)
Comments No remarks			