



RENAULT GRAND SCENIC
Grand Scénic dCi 110 Energy FAP eco2
Bose Edition 7 pl

VIN NO VF1JZ89BH54546492
Registration Number EA861YV



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	0	2	225964 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2016-03-31	-

Inspection Report Summary

Customer	BCA Auto Encheres	Mechanical Grade	
Inspection Date / Place	2026-09-02 / BCA MONTMARTIN	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Light Grey	No of Doors	5
Engine Size (cc)	1461	Seat Covering	
Body Type	MPV	Drive Train	Front
NEDC CO2 Rating (g/km)	105	No of Seats	7
Engine Rating CV	5	Metalic Colour	
Accident Damage	No	Euro Emission	
Arrival Date	2026-09-01		

Vehicle History & Documents

Service Book Available	Present	Previous Usage	Normal Use
Manufacturer Warrenty		Odometer Warranty	No
Next Service Mileage	km	Imported	No

Vehicle Remarketing Imagery



Vehicle Remarketing Imagery



Equipment

Alloys wheels	Central locking	Cruise control	Electrically folding wing mirrors
Front fog lamps	Front parking sensors	Power assisted steering	Radio
Rear parking sensors	Roof rails	Satellite navigation	Stability control

Equipment Details


Presence Anti-Theft Lock Nut	Ok	Air Conditioning	Yes
Seat Heating	No	Sunroof Type	Tilt/Slide Glass

Wheels & Tyres


Left Rear Tyre Depth	5	Left Front Tyre Depth	3
Right Rear Tyre Depth	5	Right Front Tyre Depth	3

Cosmetic Damage

17 Identified damages



1 Identified damages



Component		Damage	Comments
1	Hood	Bodywork / Dent / Hail Area	
2	Door / Front Right	Paint / Scratch / Line	
3	Door / Back Right	Paint / Scratch / Line	
4	Door / Back Left	Bodywork / Dent / Hail Area	
5	Fender / Back Left	Bodywork / Dent / Hail Area	
6	Corner Bumper / Front Right	Paint / Scratch / Line	
7	Roof	Bodywork / Dent / Hail Area	
8	Door / Front Left	Bodywork / Dent / Hail Area	
9	Exhaust / Left	Paint / Scratch / Line	
10	Rim / Back Right	Out of Bodywork / Scratch	
11	Rim / Front Right	Out of Bodywork / Scratch	

12	Rim / Back Left	Out of Bodywork / Scratch
13	Rim / Front Left	Out of Bodywork / Scratch
14	Corner Bumper / Back Right	Paint / Scratch / Line
15	Seat / Front Left	Interior / Ripped
16	Exhaust / Left	Missing Part
17	Windshield / Front	Glass Break / Impact
18	Windshield / Front	Glass Break / Impact

Vehicle Condition Imagery



1. Hood
Bodywork / Dent / Hail Area -



2. Door / Front Right
Paint / Scratch / Line -



3. Door / Back Right
Paint / Scratch / Line -



4. Door / Back Left
Bodywork / Dent / Hail Area -



5. Fender / Back Left
Bodywork / Dent / Hail Area -




6. Corner Bumper / Front Right
Paint / Scratch / Line -

Vehicle Condition Imagery



7. Roof
Bodywork / Dent / Hail Area -



8. Door / Front Left
Bodywork / Dent / Hail Area -



9. Exhaust / Left
Paint / Scratch / Line -



10. Rim / Back Right
Out of Bodywork / Scratch -



11. Rim / Front Right
Out of Bodywork / Scratch -



12. Rim / Back Left
Out of Bodywork / Scratch -

Vehicle Condition Imagery



13. Rim / Front Left
Out of Bodywork / Scratch -



14. Corner Bumper / Back Right
Paint / Scratch / Line -



15. Seat / Front Left
Interior / Ripped -



16. Exhaust / Left
Missing Part -



17. Windshield / Front
Glass Break / Impact -



18. Windshield / Front
Glass Break / Impact -

Mechanical Condition

Levels

Oil Condition		Level - Oil	
Coolant Fluid - Condition		Coolant Fluid level	
Brakes Fluid			

Engine

Cross Member		Serpentine Belt	
Control Liquid Leak			

Equipments Test

Main & Spare Keys Functioning		Parking Sensors / Cameras Functioning	
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test		Dump / Trail / Tail Gate Lift	
Electric Windows		Audio Equipment	
Navigation System		AC / Heating System	
Central Locking			

Dashboard Lights

ABS Warning Light		Transmission Warning Light	
Diesel Particulate Filter Light		ESP Fault/Traction Control Malfunction Light	
4WD Light		Service Light	
Dashboard Working		Engine Light	
Oil Pressure Warning Light		Airbag Warning Light	
Brake Warning Light		Steering Fluid Level	
Level - Fuel / Battery	5		

Hybrid/EV

Charge Port Condition		Charge lead 1 condition /Charge lead 2 condition	
Hybrid System Fault			

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	✓
Transmission	✓	Clutch Functioning	✓
Brakes Functionning	✓	Steering	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.