



## Inspection Report

Customer	BCA Sweden	Cosmetic Grade	1
Registration Number	WWJ59N	Mechanical Grade	A

### Vehicle Data

#### Nissan Leaf Leaf Acenta 40 kWh - 2020

Vehicle Identification Number	SJNFAAZE1U0100555	Odometer Reading	70306 km
First Registration / Construction Year	2020-07-31 / 2020-07-01	Inspection Date / Place	2025-05-15 / Strängnäs
Fuel Type	Battery Electric Vehicle	Gearbox Type	Automatic
Colour	White	Number of Keys	2
Service Book Available	Missing	Service History	
Last Service Km / Date	- / -	Arrival Date	2025-05-13

### Mounted Tires

Tyre / Wheel Type	Four Seasons	
		//R16 / 6 mm
		//R16 / 5 mm
		//R16 / 6 mm
		//R16 / 5 mm

### Unmounted Tires

Tyre / Wheel Type	Summer	
		//R16 / 4 mm
		//R16 / 4 mm
		//R16 / 4 mm

### Equipment

• Heated steering wheel	• Bluetooth
• Cruise control	• Digital Radio
• Rain sensitive windscreen wipers	• Reversing Camera
• Satellite navigation	

### Comments Test Drive

Comment
---------

## Checklist

Stickers

Testdriven

TPMS-Warning light on

## Damage

	Component	Damage
1	Roof Upholstery	Interior / Dirty
2	Door Step / Back Left	Interior / Dented
3	Service Book	Interior / Missing
4	Glovebox	Interior / Loose
5	Rim / Front Left	Out of Bodywork / Scratch
6	Rim / Front Right	Out of Bodywork / Scratch
7	Shield / Back	Paint / Scratch / Line
8	Other	Paint / Poor Previous Repair
9	Fender / Back Right	Bodywork / Dent / Dent
10	Shield / Front	Paint / Scratch / Scuff
11	Roof	Bodywork / Dent / Hail Area

## Photo Documentation

















1. Roof Upholstery  
Interior / Dirty



2. Door Step / Back Left  
Interior / Dented





3. Service Book  
Interior / Missing



4. Glovebox  
Interior / Loose




5. Rim / Front Left  
Out of Bodywork / Scratch




6. Rim / Front Right

Out of Bodywork / Scratch




7. Shield / Back

Paint / Scratch / Line



8.

Paint / Poor Previous Repair




9. Fender / Back Right

Bodywork / Dent / Dent



10. Shield / Front

Paint / Scratch / Scuff



11. Roof

Bodywork / Dent / Hail Area