



status report

Report number:	0000000835236-EN968	Off. Mark :	SLS-DC 37
reference number:	30927430		

Vehicle Data

Hyundai Kona (OS)(2017->) Edition 30+ Elektro 2WD

Vehicle identification number .:	TMAK281HFNJ053258	mileage read:	52967 km
First Registration / construction Year:	14.03.2022 / 2022	Inspection date/place:	08.04.2025 14:22 66740 Saarlouis
Bodywork:	SUV	Body type:	hatchback
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	Hard Disk Drive	Displacement / power:	0 ccm / 100 kW (136 PS)
Drive type:	front-wheel drive	Paint:	Teal Blue / MET
Type of paint:	Metallic	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	2025-03 / 2025-03
cushion type:	Substance	Service book available:	Yes
Interior Color:	Gray	Maintained service book:	No
smoking vehicle:	No	Last service km / on the:	29218 / 2023-11-20
Vehicle roadworthy:	Yes	Submitted vehicle documents:	Registration Certificate
State outside:	2 - Good	condition inside:	2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Mounted tires

	All weather tire	Aluminium original
Tyre / wheel type:		/// 6 mm
2nd axis - Left / states .		/// 6 mm
2nd axis - right / states .		/// 7 mm
1st axis - Left / states .		/// 7 mm
1st axis - right / states .		/// 7 mm
Traffic Safety:	Roadworthy	

Series

- Storage bag on front seat backrests
- Airbag front passenger side can be switched off
- Active brake light (ESS)
- Anti-lock braking system (ABS)
- Audio system: Radio RDS
- Exterior mirror painted
- Roof rails
- Digital Cockpit (Instrumentenanzeige Digital)
- Automatic switch-on for driving lights / light sensor
- Elektromotor 100 kW (cont. 26 kW)
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Driver assistance system: Driving profile selection (Drive Mode)
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Driving assistance system: lane departure warning system (LDWS, Lane Departure Warning System)
- Electric window lift at the front
- Handsfree Bluetooth
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Getriebe für Elektrofahrzeug
- Pretensioners
- Isofix seats for child seat
- Airbag passenger side
- Airbag driver side
- Alarm system
- Drive type: front-wheel drive
- Outside mirror electr. adjustable and heated, both
- Brake Assist
- Roof spoiler
- Rear Parking Sensors
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driver assistance system: hill start assist
- Fahrassistenz-System: Insassenalarm (ROA)
- Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)
- Electric window rear
- Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik
- Windscreen with band filter on top
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Cup holder in front
- Rear window heatable
- Body: 5-door

- | | |
|--|---|
| <ul style="list-style-type: none"> • Climate • Headrests adjustable at the back • Charging cable with Type 2 plug • Lumbar support seat front left, electr. adjustable • Steering wheel with multifunction • Steering column (steering wheel) height adjustable • Reading light • Center armrest front with compartment • Navigations-Paket • Parking brake electric (EPB) • Radstand 2600 mm • Tire pressure monitoring system • Rear seat back divided / foldable • Shift / selector lever handle leather • Side airbag in front • Seatbelts height adjustable • Seat cover / upholstery: fabric • Smartphone Schnittstelle (Apple CarPlay & Android Auto) • Sun visors with mirror (illuminated) • Start / Stop system • Touchscreen-Farbdisplay (8,0 Zoll) • Türgriffe innen silber • Glazed tinted • Seat belt warning system, driver / passenger side • Heat pump for heating/air conditioning • Central locking with remote control | <ul style="list-style-type: none"> • Head airbag system • Kühlergrill Wagenfarbe • Ladevorrichtung On-Board-Lader (3-Phasen) • Steering wheel (leather) with multifunction • Steering wheel with paddle shifters • Steering column (steering wheel) longitudinally adjustable • LM rims • Facelift • Notladekabel (ICCB) • Radio reception digital (DAB +) • Tire repair kit • Backup camera • Schalt-/Wählhebel (Shift by Wire) • Window fogging detection / control • Power steering • Seat front left height adjustable • Smart key • Sonderlackierung Dive in Jeju Uni • Start-stop button • Daytime running light LED • Door handles outside body color • USB port + AUX-IN port • Verglasung hinten abgedunkelt (Privacy Glass) • Immobilizer (electronic) • Wärmeschutzverglasung |
|--|---|

Special Features

- Mica finish / mineral effect finish

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General exam

test drive:

Conducted limited

Because of the conditions a short test drive could be performed only at a moderate speed .
As part of the test drive further tests were carried out. The results are documented later in the report .

Subfloor Inspection:	Not performed A visit to the underbody of the car was not performed .
Mileage plausible:	Not testable Not testable
reference:	
Note Road Safe:	

Accident claims investigation	
Rep. Predamages / -height gross:	
Layers of paint thickness measurement:	
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview of technical examination					
Air conditioning:	Examined limited	✗	Lighting system:	examined limited	✗
Sunroof / convertible:	unavailable	✗	Seat heating:	Not checked	✗
Brake system:	examined limited	✗	Engine running:	examined limited	✗

Implemented technical examination	
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
Sunroof / convertible:	unavailable
Seat heating:	Not checked
brake system:	The braking system has been tested by a visual inspection .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
reference:	*Serviceintervall nach Herstellervorgaben überzogen (12 Monate / 15.000 km) Service 11/2024 nicht durchgeführt. Wertminderung sowie Verlust der Herstellergarantie und jeglicher Kulanz.

Damage			
 Exterior and Styling			
	Component	Damage	Rep kind
1.	Windshield	Wear and tear	Without repair
 Others			
	Component	Damage	Rep kind
2.	main inspection	Due	Replace
3.	maintenance	Due	Replace

4.	Serviceintervall nicht gepflegt -Wertminderung	Not okay
----	---	----------

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside



instrument cluster




mileage



center console



key



Service book / proof



Others



Hüsge Gruppe®
Die Gutachter



engine compartment



rims



tires



tires



tires



tires



1. Windshield

Wear and tear - Without repair