





status report

Report number: 0000000775780-EN926 Off. Mark : ZW-DM99E

reference number: 30751257

Vehicle Data

Hyundai Kona (OS)(2017->) Advantage Elektro 2WD

Vehicle identification number .: KMHK281HFLU116412 mileage read: 31149 km

First Registration /

09.07.2024 11:59 66497

construction Year: 25.03.2021 / 2020 Inspection date/place: Contwig

Bodywork: SUV Body type: hatchback

fuel: Electric drive Transmission type: Automatic

GPS sat nav disk: Hard Disk Drive Displacement / power: 0 ccm / 100 kW (136 PS)

Engine: front-wheel drive Paint: White

Type of paint: Metallic Doors / seats: 5/5

Number of keys: 2 Next HU / AU: 2024-03 / 2024-03

cushion type: Substance Service book available: Yes
Interior Color: Black Maintained service book: -

smoking vehicle: No Last service km / on the: 31148 / 2024-03-25

Vehicle roadworthy: Yes Submitted vehicle documents: Registration Certificate

State outside: 2 - Good condition inside: 2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.





Report number: 0000000775780-EN926 www.huesges-gruppe.de page: 1 from 7



| Mounted tires | | | |
|-----------------------------|--------------|---------------------|--|
| Tyre / wheel type: | Summer tires | Aluminium original | |
| 1st axis - Left / states . | Michelin | 215/55/R17/94V 6 mm | |
| 1st axis - right / states . | Michelin | 215/55/R17/94V 6 mm | |
| 2nd axis - Left / states . | Michelin | 215/55/R17/94V 6 mm | |
| 2nd axis - right / states . | Michelin | 215/55/R17/94V 6 mm | |
| Traffic Safety: | Roadworthy | | |

Series

- 3rd brake light
- Airbag front passenger side can be switched off
- Alarm system
- Drive type: front-wheel drive
- Outside mirror electr. adjustable and heated, both
- Flashing light integrated in the exterior mirror
- Roof rails
- Automatic switch-on for driving lights / light sensor
- Elektromotor 100 kW (cont. 26 kW)
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Electric window rear
- Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik
- Windscreen with band filter on top
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage compartment cover / roller blind
- Getriebe für Elektrofahrzeug
- Rear window heatable
- Instrumente mit Farbdisplay 3,5 Zoll
- Body: 5-door
- Head airbag system
- Kühlergrill schwarz (mattlackiert)
- Steering wheel (leather) with multifunction
- Reading light
- LM rims

- Airbag passenger side
- Airbag driver side
- Anti-lock braking system (ABS)
- Audio system: Radio RDS
- Exterior mirror painted
- Brake Assist
- Rear Parking Sensors
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driver assistance system: hill start assist
- Electric window lift at the front
- Handsfree Bluetooth
- Frontscheibe wärmedämmend
- Gepäck-/Laderaumleuchte
- Cruise control system (tempomat) with distance control ACC
- Cup holder in front
- Innenausstattung: Luftdüsen farbig
- Isofix seats for child seat
- Climate
- Headrests adjustable at the back
- Charging cable with Type 2 plug
- Lenkrad heizbar
- Lifetime MapCare (Internetbasierende Dienste)
- Center armrest front with compartment



| Navigation system | • Radio reception digital (DAB +) |
|--|---|
| • Radstand 2600 mm | • Tire repair kit |
| Tire pressure monitoring system | Backup camera |
| Rear seat back divided / foldable | Shift / selector lever handle leather |
| Side airbag in front | Darkened side windows from the B-pillar |
| Power steering | Seat front left height adjustable |
| Seat cover / upholstery: fabric | Heated seats in the front |
| Sonderlackierung Galaxy Gray Metallic | Sun visors with mirror (illuminated) |
| Start / Stop system | Daytime running light LED |
| Touchscreen-Farbdisplay (8,0 Zoll) | Door handles outside body color |
| Türgriffe innen verchromt | USB port + AUX-IN port |
| Glazed tinted | • Immobilizer (electronic) |
| Heat pump for heating/air conditioning | Central locking with remote control |

Special Features

Metallic paint

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

| General exam | |
|----------------------|---|
| test drive: | Conducted limited |
| | Because of the conditions a short test drive could be performed only at a moderate speed . |
| | As part of the test drive further tests were carried out. The results are documented later in |
| | the report . |
| Subfloor Inspection: | Not performed |
| | A visit to the underbody of the car was not performed . |
| Mileage plausible: | Not testable |
| | Not testable |
| reference: | |
| Note Road Safe: | |

Accident claims investigation

Rep. Predamages / -height gross:

Layers of paint thickness

measurement:

Existing collision damage: Not established

On the vehicle body shell were on visual examination found no existing accident damages

(other than the usual signs of use) .

reference:

Overview of technical examination

Report number: **0000000775780-EN926 www.huesges-gruppe.de** page: 3 from 7



examined limited

Air conditioning: Lighting system: **Examined limited** examined limited Sunroof / convertible: Seat heating: unavailable Not checked Brake system: **Engine running:**

Implemented technical examination

air conditioning: The air conditioning system could be tested only restricted during the visit.

lighting system: The Lichtanlange could be considered limited to the tour date .

examined limited

Sunroof / convertible: unavailable Seat heating: Not checked

brake system: The braking system has been tested by a visual inspection.

engine running: Checking the engine running was limited. Here no audible or visual abnormalities were noted.

reference:

Damage

1.



Component Rep kind **Damage** center console Wear and tear Without repair

Others

Rep kind Component **Damage**

Herstellergarantie Not looked after

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage related wear, as in normal use are inevitable (small bumps, dents, scratches).

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .

0000000775780-EN926 www.huesges-gruppe.de page: 4 from 7 Report number:



Photo documentation



front Left



rear Left



Inside



front Right



rear Right



trunk





instrument cluster



center console



engine compartment



mileage



rims



key





Service book / proof



tires



tires



Others



tires



tires