



Huesges Gruppe®
Die Gutachter

status report

Report number: 0000000814525-EN926
reference number: 30859935

Off. Mark : LF-T 76E

Vehicle Data

Hyundai Kona (OS)(2017->) Trend Elektro 2WD

Vehicle identification number .:	KMHK381HFMU124822	mileage read:	45585 km
First Registration / construction Year:	29.06.2021 / 2021	Inspection date/place:	23.12.2024 Dieselstraße 3, 85386 Eching
Bodywork:	Cars	Body type:	Road /
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	Hard Disk Drive	Displacement / power:	0 ccm / 100 kW (136 PS)
Drive type:	front-wheel drive	Paint:	Ignite Flame / SOL
Type of paint:	Uni	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	2026-08 / 2026-08
cushion type:	Substance	Service book available:	Yes
Interior Color:	Gray	Maintained service book:	partially
smoking vehicle:	No	Last service km / on the:	42555 / 2024-08-28
Vehicle roadworthy:	Yes	Submitted vehicle documents:	
State outside:	2 - Good	condition inside:	2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Mounted tires

	Winter tires	Aluminum
Tyre / wheel type:		
1st axis - Left / states .	Dunlop	215/55/R17/98V 6 mm
1st axis - right / states .	Dunlop	215/55/R17/98V 6 mm
2nd axis - Left / states .	Dunlop	215/55/R17/98V 6 mm
2nd axis - right / states .	Dunlop	215/55/R17/98V 6 mm
Traffic Safety:	Roadworthy	

Unmounted tires

	Summer tires	Aluminum
Tyre / wheel type:		
1st axis - Left / states .	Michelin	215/55/R17/94V 4 mm
1st axis - right / states .	Michelin	215/55/R17/94V 4 mm
2nd axis - Left / states .	Michelin	215/55/R17/94V 4 mm
2nd axis - right / states .	Michelin	215/55/R17/94V 4 mm
Traffic Safety:	Roadworthy	

Series

- | | |
|---|---|
| <ul style="list-style-type: none"> • 3rd brake light • Airbag • Airbag driver • Anti- lock braking system (ABS) • Audio System Radio RDS
Smartphone Schnittstelle (Apple CarPlay & Android Auto), Color touchscreen display (7.0 inches) • painted mirrors • brake Assist • rear Parking Sensors • Electr . Brakeforce Distribution • Electron. Stability Control (ESC) with Brake Assist | <ul style="list-style-type: none"> • 6 speakers
tweeter • Airbag switched off • alarm system • Drive Front Wheel Drive • Power side mirrors . adjustable and heated, both • Indicator integrated into mirrors • roof rails • Off switch for driving light / light sensor • Electric motor 100 kW (cont. 26 kW) • Driving assistance system: active lane keeping assistant (LKAS, Lane Keep Assist System) |
|---|---|

- | | |
|--|---|
| <ul style="list-style-type: none"> • Driving assistance system: attention assistant • Hill Start Assist • Electric window . behind • handsfree Bluetooth • Baggage / cargo area lamp • Luggage compartment cover / shade • Transmission for electric vehicle • heated rear window • Isofix admissions for child seat • Climate Control • Rear headrests adjustable • Lumbar support front left seat , electric. adjustable • heated steering wheel • reading Light • LM rims • Emergency charging cable (ICCB) • Digital radio reception (DAB+) • Tire repair kit • Rear View Camera • Gearshift / selector lever leather • Front Side Airbags • Front left seat height adjustment • Heated front seats • Special paint finish Galaxy Gray Metallic • Start-stop button • LED daytime running lights • Exterior door handles body color • USB + AUX - IN connection • Immobiliser (electronic) | <ul style="list-style-type: none"> • Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
Driving assistance system: Autonomous emergency braking function including pedestrian detection (FCA-Ped.), Driving assistance system: Autonomous emergency braking function including cyclist detection (FCA- Cyc.) • Driving assistance system: safety system with automatic emergency call (ERA GLONASS / eCall) • Electric windows front • Counter- steering assist (Vehicle Stability Management , VSM) • Cargo net in the trunk / cargo area • Cruise control system (cruise control) with distance control ACC • Cup holders front • Instruments with 3.5 inch color display • Body 5-door • Head airbag system • Body color grille • Steering wheel (leather) with multifunction • Steering wheel with paddles • Headlamp leveling • Front center armrest with compartment • Electric parking brake (EPB) • Wheelbase 2600mm • Tire Pressure Monitoring System • Rear seat backrest split / folding • Window fogging detection / control • power steering • Seat cover / upholstery fabric • Smart Key • Sun visors with mirrors (illuminated) • Start / Stop system • Trend package • Chrome interior door handles • tinted glazing • Central locking with remote control |
|--|---|

Special Features

- Navigation Package
Sound-System KRELL, 8 speakers, subwoofer, Smartphone Schnittstelle
(Apple CarPlay & Android Auto), navigation system, Service system:
Remote Services (Blue Link), Touchscreen color display (10.25 inch)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General exam

test drive:	Conducted limited Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .
Subfloor Inspection:	Not performed A visit to the underbody of the car was not performed .
Mileage plausible:	Yes Yes
reference:	
Note Road Safe:	

Accident claims investigation

Rep. Predamages / -height gross:	No detectable A visual inspection of the outer body skin did not reveal any previous damage.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview of technical examination

Air conditioning:	Examined limited	✓	Lighting system:	examined limited	✓
Sunroof / convertible:	unavailable	✗	Seat heating:	Not checked	✗
Brake system:	examined limited	✓	Engine running:	examined limited	✓

Implemented technical examination

air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
Sunroof / convertible:	unavailable
Seat heating:	Not checked

brake system:	The braking system has been tested by a visual inspection .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
reference:	*Serviceintervall nach Herstellervorgaben überzogen (12 Monate / 15.000 km) Verlust der Herstellergarantie und jeglicher Kulanz möglich.

Damage



Exterior and Styling

	Component	Damage	Rep kind
1.	Roof	Subsequently painted	Without repair



Others

	Component	Damage	Rep kind
2.	Herstellergarantie	Not looked after	

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Photo documentation



front Left



front Right




rear Right



rear Left



trunk



Inside



instrument cluster




mileage



center console



key



Service book / proof



Others




engine compartment




rims



tires



tires



tires



tires



Tires



Tires



Tires



Tires



Tires



1. Roof
Subsequently painted - Without repair



Hüsches Gruppe®
Die Gutachter



1. Roof
Subsequently painted - Without repair