



SKODA OCTAVIA COMBI: GA-828-YR

Vinnumber:	TMBJG7NXXNY010025	Versionname:	SKODA OCTAVIA COMBI 2.0 TDI 116 DSG7 Business
First Registrationdate:	27/07/2021	Fiscalpower:	VP [5P] bva 7-116CH-6cv (break)
Expertise Mileage:	137387	Power Kw:	85
Bodytype:	Break	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

205/60/16/96 H				
Winter tyres:	Fr.L.	Dunlop: 50%	Fr.R.	Dunlop: 50%
	Re.L.	Dunlop: 35%	Re.R.	Dunlop: 35%
Tyre profile depth FL				4.9
Tyre profile depth FR				4.9
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace

