


### Vehicle details

VIN	KNACC81GF K5029093	Brand	KIA	Maintenance date	-
Licence Plate	H6-01-KB	Model	Niro e-Niro EV ExecutiveLine 5d	Maintenance mileage	-
Registration date	21/02/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	139 276 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

### Inspection Details

Inspection date	28/02/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



### Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓




### Removable element

Spare wheel kit	✓
Load cover	✓
Vehicle charger	✓
Wireless charger	✓





### Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

### Tyres

Michelin 215/55/17 Summer 3.5 mm		Michelin 215/55/17 Summer 4.0 mm	
Michelin 215/55/17 Summer 5.5 mm		Michelin 215/55/17 Summer 5.0 mm	

Exterior

<p>1</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) &gt; 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	<p>2</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) &gt; 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Door	Position	Back right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Bumper																						
Position	Back																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
Part	Door																						
Position	Back right																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
<p>3</p>  <p>● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) &gt; 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	<p>4</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </tbody> </table>	Part	Windscreen	Position	-	Damages	Stone impact	Severity	-	Repair mode	For info
Part	Bumper																						
Position	Front																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
Part	Windscreen																						
Position	-																						
Damages	Stone impact																						
Severity	-																						
Repair mode	For info																						