

# INSPECTION REPORT


**End of contract**

## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 316528                         |
| License plate                 | 1XNM684                        |
| Vehicle identification number | VF72CYHXXL4118907              |
| Dossier                       | 2019 256 112                   |
| Make                          | Citroen C3 Aircr.1.5BHDi 120 S |
| Mileage                       | 177569                         |
| First registration            | 20/02/2020                     |
| client availability date      | 29/06/2026                     |
| inspectionDate                | 14/07/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | Y       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | N       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |






## DAMAGES

| Damages | Type                                                  | Acceptable |
|---------|-------------------------------------------------------|------------|
| 11      | Bumper Front // Smart Repair Medium                   | N          |
| 18      | Bumper Front / Spoiler / Replace                      | N          |
| 41      | Windshield // Replace                                 | Y          |
| 67      | Wing Front Left / Trim / Replace                      | N          |
| 80      | Door Front Left // Smart Repair Small                 | N          |
| 89      | Door Front Left / Window / Replace                    | Y          |
| 98      | Rocker Panel Left / Cover Not Painted / Replace       | Y          |
| 103     | Door Rear Left // Painting                            | Y          |
| 109     | Door Rear Left / Window / Replace                     | Y          |
| 117     | Wing Rear Left / Trim / Replace                       | Y          |
| 124     | Light / Rear left / Replace                           | N          |
| 136     | Bumper Rear // Polish                                 | Y          |
| 138     | Bumper Rear / Lower Cover Not Painted / Replace       | Y          |
| 159     | Rear Bonnet / Rear Window / Replace                   | Y          |
| 162     | Roof // Painting                                      | N          |
| 187     | Wing Rear Right / Trim / Replace                      | N          |
| 194     | Door Rear Right // Repair & Painting                  | Y          |
| 199     | Door Rear Right / Window / Replace                    | N          |
| 201     | Rocker Panel Right // Smart Repair Medium             | Y          |
| 214     | Door Front Right // Repair & Painting                 | Y          |
| 219     | Door Front Right / Window / Replace                   | Y          |
| 237     | Wing Front right / Trim / Replace                     | Y          |
| 320     | Wheel Two Tone Rear Left // Repair                    | Y          |
| 340     | Wheel Two Tone Front Right // Repair                  | N          |
| 594     | Trunk Lid Interior Coating / Complete Panel / Replace | Y          |
| 631     | Rear Left Door Interior Coating // Repair             | N          |
| 860     | Interior Cleaning // Small                            | N          |

## Damage Pictures



Door Front Right / Window / Replace-scratch




Door Rear Right / Window / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear left / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Rocker Panel Left / Cover Not Painted / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch





Wing Rear Left / Trim / Replace-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Windshield // Replace-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Smart Repair Medium-scratch



Wing Front right / Trim / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Left / Window / Replace-scratch




Door Rear Left / Window / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Rocker Panel Right // Smart Repair Medium-dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Roof // Painting-Chemical reaction



Interior Cleaning // Small-stain