


Damage Report



Kia Niro ExecutiveLine - Electric - Automatic - 204 hp - 155.674 km

Licence plate: J137HG - VIN: *****

Damage locations



Normal damage

1. Front Bumper:	● Scratch
2. Hood/Bonnet:	● Scratch
3. Windshield/Windscreen:	● Scratch
4. Front Left Door:	● Scratch
5. Rear Left Door:	● Scratch
6. Left Quarter Panel:	● Scratch
7. Rear Bumper:	● Scratch
8. Roof:	● Scratch
8. Roof:	● Dent
8. Roof:	● Corrosion
9. Right Quarter Panel:	● Scratch
10. Rear Right Door:	● Scratch
10. Rear Right Door:	● Dent
11. Front Right Door:	● Scratch
11. Front Right Door:	● Dent
12. Right A Pillar:	● Scratch
13. Front Right Fender/Wing:	● Scratch

Body damage

4. Front Left Door:	●
5. Rear Left Door:	●

Comments

service expired