



PEUGEOT 3008: FY-236-PX

Vinnumber:	VF3MCYHZUMS112383	Versionname:	PEUGEOT 3008 BlueHi 130 S&S EAT8 Active Busine
First Registrationdate:	15/04/2021	Fiscalpower:	VP [5P] bva 8-130CH-7cv (SUV)
Expertise Mileage:	160006	Power Kw:	96
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

215/65/17/103 V				
Summer tyres:	Fr.L.	Continental: 80%	Fr.R.	Continental: 80%
	Re.L.	Continental: 80%	Re.R.	Continental: 75%
Tyre profile depth FL				2.9
Tyre profile depth FR				2.9
Tyre profile depth RL				3.0
Tyre profile depth RR				3.4
Tyre size FL				215/65 R 17 103 V
Tyre size FR				215/65 R 17 103 V
Tyre size RL				215/65 R 17 103 V
Tyre size RR				215/65 R 17 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Armrest F M, Tear, Replace



Interior, Stain, Cleaning



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim FL, Missing, Replace



Door RL, Scratch(es), Acceptable



Bumper F, Scratch(es), Paint



Bumper spoiler F, Scratch(es), Replace



Bumper moulding F, Broken, Replace and paint



Bonnet, Stone chip(s), Paint



Door FR, Bad repair, Paint



Wing trim RR, Scratch(es), Replace



Wing RR, Scratch(es), Polish



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Deformed / Strained, Repair and paint (complete)

