MACMDAM









RENAULT ZOE: FX-224-ME

Vinnumber: VF1AG000466797356 First Registrationdate: 26/02/2021 Expertise Mileage: 31452 Bodytype: Berline Gearbox: Automatic Transmission: Front Fueltype: Electric Engine functioning Yes Battery functioning Yes Vehicle running Yes Number of doors 5 Number of seats 2 Number head rests 2 Type of rims (mounted) Aluminium Versionname: RENAULT ZOE Intens R135 - Achat Intã@gral -2020 VF [5P] 1-135CH-1cv (bi-corps VU)

 Fiscalpower:
 99

 Power Kw:
 99

 Body colour
 White

 Paint type
 Metalic

 Interior colour
 Black

 Type of rims (mounted)
 Aluminium

 Dashboard color
 Black

Options

Category

Number of keys total Number keys remote GPS big screen color Windows electric F Windows electric R Cruise Control

Steering wheel multifunctional Steering wheel leather

2 Radio

٧s

2 Luggage cover

Headlights Xenon/LED/Laser Front parking sensors Rear parking sensors Rear view camera Seat cover lining

lining Lining Other
Lining Semi-leather

Summer

255

255

255

255

Bridgestone: 45%

Type of climate control Autom climate control

Bridgestone: 50%

195/55/16/91 V

Tyres

Summer tyres:

	Re.L.	Bridgestone: 40%	Re.R.	Bridgestone: 35%
Tyre profile depth FL				5.0
Tyre profile depth FR	1			5.2
Tyre profile depth RL	-			5.7
Tyre profile depth RF	t .			5.8
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer

Assistance equipment

Tyre type RR

Tyre make FL

Tyre make FR

Tyre make RL

Tyre make RR

Number of charging cables (normal)

Number of charging cables (rapid charge)

Seat cover FL, Tear, Replace





Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)







Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)







Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)







Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)









Wing RL, Bad repair, Paint






Door RL, Scratch(es), Polish











Bumper F, Scratch(es), Paint













Bumper grille, Unclasped, Dismount/Mount





Wing FR, Scratch(es), Polish





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)







Door RR, Scratch(es), Polish





Bumper R, Deformed / Strained, Replace and paint







Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)





