

INSPECTION REPORT

End of contract

GENERAL INFO

File	313339
License plate	1YNC944
Vehicle identification number	VF1RFB00566343604
Dossier	2020 209 031
Make	Renault Mégane GT dCi 115 Inte
Mileage	198582
First registration	08/10/2020
client availability date	25/05/2026
inspectionDate	02/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
186	Wing Rear Right // Polish	N
193	Door Rear Right // Painting	N
213	Door Front Right // Painting	N
233	Wing Front right // Painting	N
135	Bumper Rear // Replace & Painting	N
258	Towing Cover Rear // Replace	N
14	Bumper Front // Repair & Painting	N
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
244	Light / Front Right / Replace	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
413	Seat Front Left / Rear Coating / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
624	Front Right Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	N
851	Registration Card loss Arval name //	N
860	Interior Cleaning // Small	N

Damage Pictures



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn




Seat Front Left / Rear Coating / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn




Bumper Front // Repair & Painting-bad position



Light / Front Right / Replace-cracked



Door Front Left / Trim / Replace-cracked



Front Right Door Interior Coating // Replace Completely-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wheel Two Tone Rear Right // Repair-scratch



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch



Trunk Lid Interior Coating / MDF Rear Left / Replace-scratch



Trunk Compartment / Boot Cover / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch




Wing Rear Left // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Repair & Painting-scratch + dent



Wing Front right // Painting-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Polish-scratch



Bumper Rear // Replace & Painting-scratch + dent



Towing Cover Rear // Replace-missing