

RENAULT MEGANE²BK HY

Registration	GC-874-AM
VIN	VF1RFB00567843966
Mileage	144,619 km
First registration date	27/09/2021
Body colour	Grey

INSPECTION DETAILS

Inspection address description	BCA TEA Moselle	Inspection date	08/09/2026 13:05:05
Inspection address	1 Rue de la Carrière 57445 Réding		

VEHICLE INFO

Make	RENAULT	Body type	Break
Model	MEGANE ² BK HY	Number of doors	5
VIN	VF1RFB00567843966	Number of seats	5
First registration date	27/09/2021	Transmission	Front
Mileage	144,619 km	Interior colour	Black
Category	Passenger Car	Body colour	Grey

DOCUMENTS AND MAINTENANCE

Service book	Yes	User's manual	Yes
Number of keys total	1	Registration Certificate	No
Number keys remote	1	Registration Certificate	N/A

EQUIPMENT ACCORDING TO INSPECTOR

Battery functioning	Yes	Rear view camera	Yes
Engine functioning	Yes	Luggage cover	Yes
Vehicle running	Yes	Compressor	Yes
Fuel Level	0	Repair kit	Yes
GPS big screen color	Yes	Paint type	Metalic

TIRES

Mounted Tires

Location	Position	Tread	Manufacturer	Dimensions	Tire season	Type of rims	Runflat
Front	Left	3.2 mm	Michelin	205/55 R 16 91 H	All season	Steel	No
Front	Right	1.8 mm	Michelin	205/55 R 16 91 H	All season	Steel	No
Rear	Left	5.1 mm	Michelin	205/55 R 16 91 H	All season	Steel	No
Rear	Right	5.0 mm	Michelin	205/55 R 16 91 H	All season	Steel	No

DAMAGES



Remote ignition key (no insert)

Damage type	Missing
Repair mode	Repair/replace (lump sum)



Tyre FL

Damage type	Out of tolerance
Repair mode	Replace



Tyre RL

Damage type	Tear
Repair mode	Replace



Tyre FR

Damage type	Out of tolerance
Repair mode	Replace



Rear bulkhead lining

Damage type	Scratch(es)
Repair mode	Smart repair



Boot lid covering R

Damage type	Scratch(es)
Repair mode	Smart repair



Aerial

Damage type	Broken
Repair mode	Replace



Seat cover FL

Damage type	Stain
Repair mode	Cleaning



Seat cover R

Damage type	Stain
Repair mode	Cleaning



Malfunction indicator

Damage type	Blinking
Repair mode	Check

COMMERCIAL PHOTOS

