



Inspection Report

Customer	BCA Sweden	Cosmetic Grade	2
Registration Number	EME26W	Mechanical Grade	B

Vehicle Data

KIA Niro e-Niro Advance - 2022

Vehicle Identification Number	KNACC81GFN5150616	Odometer Reading	141273 km
First Registration / Construction Year	2022-02-16 / 2022-01-01	Inspection Date / Place	2025-06-27 / Strängnäs
Fuel Type	Battery Electric Vehicle	Gearbox Type	Automatic
Colour	Black	Number of Keys	2
Service Book Available	Present	Service History	15904, 62808
Last Service Km / Date	62808 / 2023-11-11	Arrival Date	2025-06-26

Mounted Tires

Tyre / Wheel Type	Summer
	//R17 / 6 mm
	//R17 / 6 mm
	//R17 / 7 mm
	//R17 / 7 mm

Unmounted Tires

Tyre / Wheel Type	Four Seasons
	//R17 / 4 mm
	//R17 / 4 mm
	//R17 / 7 mm
	//R17 / 7 mm

Equipment

• Heated steering wheel	• Bluetooth
• Cruise control	• Digital Radio
• Electrically adjustable seats	• Rain sensitive windscreen wipers
• Rear parking sensors	• Reversing Camera
• Satellite navigation	• Front parking sensors
• Metallic colour	

Comments Test Drive

Comment Backkamera funkar ej, reversing camera faulty

Checklist

Chipped

Testdriven

TPMS-Warning light on

Service Lamp Lit


Damage

	Component	Damage
1	Other	Interior / Broken
2	Dashboard / Front	Interior / Broken
3	Door Step / Front Left	Interior / Dented
4	Center Console	Interior / Holed
5	Tire / Front Left	Paint / Scratch / Scuff
6	Rim / Front Left	Out of Bodywork / Scratch
7	Fender / Front Left	Paint / Scratch / Line
8	Door / Front Left	Paint / Scratch / Line
9	Door / Back Left	Paint / Scratch / Line
10	Rim / Back Left	Out of Bodywork / Scratch
11	Wing Expander / Back Left	Paint / Scratch / Scuff
12	Rim / Back Right	Out of Bodywork / Scratch
13	Mirror Repeater / Right	Glass Break
14	Hood	Paint / Scratch / Line
15	Windshield / Front	Glass Break / Impact
16	Shield / Front	Paint / Scratch / Line
17	Missed Service	

Photo Documentation














1.


Interior / Broken



2. Dashboard / Front
Interior / Broken



3. Door Step / Front Left
Interior / Dented




4. Center Console
Interior / Holed



5. Tire / Front Left

Paint / Scratch / Scuff

Replace 2 tires on the same. Byte av 2st däck på samma axel.



6. Rim / Front Left

Out of Bodywork / Scratch



7. Fender / Front Left

Paint / Scratch / Line



8. Door / Front Left

Paint / Scratch / Line



9. Door / Back Left

Paint / Scratch / Line



10. Rim / Back Left

Out of Bodywork / Scratch



11. Wing Expander / Back Left

Paint / Scratch / Scuff



12. Rim / Back Right

Out of Bodywork / Scratch



13. Mirror Repeater / Right

Glass Break



14. Hood
Paint / Scratch / Line



15. Windshield / Front
Glass Break / Impact



16. Shield / Front
Paint / Scratch / Line