

# APPRAISAL REPORT



## IDENTIFICATION VEHICLE

Driver name: HM Tongeren  
Make: RENAULT  
Model / version: KANGOO EXPRESS  
Vin: VF1WF000368148564  
Plate: 2BHZ394  
Mileage: 79336  
First registration: 02/12/2021  
Color:



## ADDITIONAL INFORMATION






Category:  
Transmission:  
Interior color:  
Metallic paint: ?  
Type of lining:  
Board computer reset: ?

## DOCUMENTS

Certificate of conformity: ✓  
Registration certificate: ✓  
Registration certificate 2: ✓  
Insurance certificate: ?  
Maintenance book:  
Number of keys: 2  
Original key: ✓

## PICTURES





## VIN INFORMATION

### EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	?	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	?
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:		Fast charging cables:	

### TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			All-seasons		?
Front right	5 mm			All-seasons		?
Rear left	5 mm			All-seasons		?
Rear right	5 mm			All-seasons		?

### DAMAGES SUMMARY

**NOT ACCEPTABLE / TO BE INVOICED**

#	Location	Damage type
1	Bumper corner RR	Scratch(es)
2	Bumper R	Broken
3	Wing RR	Dent(s) and scratch(es)
4	Wing trim RR	Missing
5	Door FR	Dent(s) and scratch(es)
6	Bumper F	Dent(s) and scratch(es)
7	Outside rear-view mirror housing L	Scratch(es)
8	Door FL	Dent(s) and scratch(es)
9	Door RL	Dent(s)
10	Wing RL	Dent(s) and scratch(es)
11	Inner door sill FL	Scratch(es)

**Total: 11**

**ACCEPTABLE / NOT TO BE INVOICED**

#	Location	Damage type	Renta®	Repaired	Already invoiced
<b>No damages present</b>					

**DAMAGES DETAILS**

1 - Bumper corner RR - Scratch(es)




2 - Bumper R - Broken



3 - Wing RR - Dent(s) and scratch(es)



4 - Wing trim RR - Missing



5 - Door FR - Dent(s) and scratch(es)



6 - Bumper F - Dent(s) and scratch(es)



7 - Outside rear-view mirror housing L - Scratch(es)



8 - Door FL - Dent(s) and scratch(es)



9 - Door RL - Dent(s)



10 - Wing RL - Dent(s) and scratch(es)



11 - Inner door sill FL - Scratch(es)



**SIGNATURE**

---

**Expert**

26/01/2026 10:34

A handwritten signature in black ink, consisting of several overlapping loops and lines.