



HYUNDAI KONA

Kona Electrique 39 kWh - 136 ch Creative

VIN NO TMAK381HFNJ062473
Registration Number GH677RT



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	68575 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-12-13	55502	2022-07-26	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251023134223
Inspection Date / Place	2025-10-23 / BCA TOULOUSE	Cosmetic Grade	1


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Battery Electric Vehicle	Gearbox Type	CVT (constantly varying transmission)
Colour	Black	Engine Size (cc)	
Engine Size		No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Media
Unavailable

Equipment

Central locking	Radio	Alloys wheels	Cruise control
Roof rails	Electrically folding wing mirrors	Rear parking sensors	Stability control
Power assisted steering	Satellite navigation		

Equipment Details


Seat Heating	Front	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres


Left Rear Tyre Depth	6	Left Front Tyre Depth	4
Right Rear Tyre Depth	6	Right Front Tyre Depth	4

Cosmetic Damage

5 Dommages




1 Dommages



Component		Damage	Comments
1	Side Panel / Back Left	Paint / Scratch / Line	
2	Seat / Back Center	Interior / Dirty	
3	Mirror Repeater / Left	Paint / Scratch / Line	
4	Door / Back Left	Paint / Scratch / Line	
5	Roof Rack / Left	Paint / Chipping	
6	Door / Front Left	Paint / Scratch / Line	



1. Side Panel / Back Left
Paint / Scratch / Line -



2. Seat / Back Center
Interior / Dirty -



3. Mirror Repeater / Left
Paint / Scratch / Line -



4. Door / Back Left
Paint / Scratch / Line -



5. Roof Rack / Left
Paint / Chipping -



6. Door / Front Left
Paint / Scratch / Line -

Mechanical Condition

Levels

Oil - Condition	NA	Level - Oil	Not available
Coolant Fluid - Condition	✓	Coolant Fluid	✓
Brakes Fluid	✓		

Engine

Cross Member	✓	Serpentine Belt	NA
Control Liquid Leak	✓		

Equipments Test

Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	AC / Heating System	✓
Parking Sensors / Cameras Functioning	✓	Central Locking	✓
Navigation System	✓		

Tyres

Presence Anti-Theft Lock Nut	✓
------------------------------	---

Dashboard Lights

ABS Warning Light	✓	Transmission Warning Light	✓
Diesel Particulate Filter Light	NA	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Service Light	✓
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	!	Airbag Warning Light	✓
Brake Warning Light	✓	Level - Fuel / Battery	90
Steering Fluid Level	NA		

Hybrid/EV

Charge Port Condition	✓	Charge lead 1 condition /Charge lead 2 condition	✓
-----------------------	---	--	---

Hybrid System Fault ✓

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	NA
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	NA
Transmission	✓	Clutch Functioning	NA
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.