



Inspection Report

Customer	BCA Sweden	Cosmetic Grade	2
Registration Number	DLH75L	Mechanical Grade	B

Vehicle Data

KIA Soul E-SOUL GLS Aut - 2020

Vehicle Identification Number	KNAJ3811FL7005315	Odometer Reading	106558 km
First Registration / Construction Year	2019-10-03 / 2019-08-01	Inspection Date / Place	2025-09-05 / Strängnäs
Fuel Type	Battery Electric Vehicle	Gearbox Type	Automatic
Colour	Red	Number of Keys	2
Service Book Available	Present	Service History	4022, 12443, 33792, 53705, 72092, 90808
Last Service Km / Date	90808 / 2024-11-26	Arrival Date	2025-09-04

Mounted Tires

Tyre / Wheel Type	Summer
	//R17 / 5 mm
	//R17 / 5 mm
	//R17 / 5 mm
	//R17 / 5 mm

Unmounted Tires

Tyre / Wheel Type	Studded
	//R17 / 7 mm
	//R17 / 7 mm
	//R17 / 7 mm
	//R17 / 7 mm

Equipment

- | | |
|------------------------------------|------------------------|
| • Heated steering wheel | • Bluetooth |
| • Cruise control | • Digital Radio |
| • Enhanced speaker system | • LED Headlamps |
| • Rain sensitive windscreen wipers | • Rear parking sensors |
| • Reversing Camera | • Satellite navigation |
| • Metallic colour | |

Comments Test Drive

Comment

Checklist

Breaks Noise	Front Noise
Chipped	Testdriven
Rear Noise	Service Lamp Lit

Damage

	Component	Damage
1	Seat / Front Right	Interior / Stained
2	Panel Filling / Back Right	Interior / Dented
3	Belt / Back Left	Interior / Worn - out
4	Panel Filling / Front Left	Interior / Dented
5	Tailgate Upholstery / Back	Interior / Missing
6	Windshield / Front	Glass Break / Impact
7	Rocker Panel / Center Left	Paint / Scratch / Scuff
8	Tailgate	Bodywork / Dent / Deformation
9	Door / Front Right	Paint / Scratch / Scuff
10	Shield / Front	Paint / Scratch / Scuff
11	Hood	Paint / Stone Chip
12	License Plate / Front	Out of Bodywork / Breakage
13	Missed Service	

Photo Documentation


















1. Seat / Front Right

Interior / Stained




2. Panel Filling / Back Right

Interior / Dented




3. Belt / Back Left

Interior / Worn - out



4. Panel Filling / Front Left

Interior / Dented



5. Tailgate Upholstery / Back

Interior / Missing



6. Windshield / Front

Glass Break / Impact




7. Rocker Panel / Center Left

Paint / Scratch / Scuff




8. Tailgate

Bodywork / Dent / Deformation




9. Door / Front Right

Paint / Scratch / Scuff



10. Shield / Front

Paint / Scratch / Scuff



11. Hood

Paint / Stone Chip



12. License Plate / Front

Out of Bodywork / Breakage