



IDENTIFICATION VEHICLE

Driver name: HM Tongeren
Make: RENAULT
Model / version: KANGOO EXPRESS
Vin: VF1WF000666982601
Plate: 2AGA475
Mileage: 67096
First registration: 23/03/2021
Color:


ADDITIONAL INFORMATION





Category:
Transmission:
Interior color:
Metallic paint: ✖
Type of lining:
Board computer reset: ✖

DOCUMENTS

Certificate of conformity: ✔
Registration certificate: ✔
Registration certificate 2: ✔
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✔

PICTURES





VIN INFORMATION

EQUIPMENT

| | | | |
|----------------------|---|-----------------------|---|
| Board computer: | ? | Central locking: | ? |
| Compressor: | ✗ | Cruise control: | ? |
| Gps: | ? | Power steering: | ? |
| Rear parking sensor: | ? | Repair kit: | ✗ |
| Front seats heated: | ? | Steering wheel: | ? |
| Electric windows: | ? | Climate control type: | |
| Headlighting type: | | Tow bar type: | |
| Charging cables: | 0 | Fast charging cables: | 0 |

TIRES

| Position | Depth | Brand | Dimensions | Type | Rims | Runflat |
|-------------|-------|-------|------------|-------------|-------|---------|
| Front left | 1 mm | | | All-seasons | Steel | ? |
| Front right | 1 mm | | | All-seasons | Steel | ? |
| Rear left | 4 mm | | | All-seasons | Steel | ? |
| Rear right | 4 mm | | | All-seasons | Steel | ? |

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

| # | Location | Damage type |
|----|--------------------------------------|-------------------------|
| 1 | Spare wheel | Missing |
| 2 | Bumper R | Broken |
| 3 | Rear light R | Broken |
| 4 | Door FR | Dent(s) and scratch(es) |
| 5 | Outside rear-view mirror R, complete | Broken |
| 6 | Bumper F | Broken |
| 7 | Wing FL | Scratch(es) |
| 8 | Outer sill L | Deformed / Strained |
| 9 | Door FL | Dent(s) and scratch(es) |
| 10 | Outside rear-view mirror housing L | Broken |
| 11 | Side wall RL | Dent(s) and scratch(es) |

Total: 11

ACCEPTABLE / NOT TO BE INVOICED

| # | Location | Damage type | Renta® | Repaired | Already invoiced |
|--------------------|----------|-------------|--------|----------|------------------|
| No damages present | | | | | |

DAMAGES DETAILS

1 - Spare wheel - Missing



2 - Bumper R - Broken



3 - Rear light R - Broken



4 - Door FR - Dent(s) and scratch(es)



5 - Outside rear-view mirror R, complete - Broken



6 - Bumper F - Broken



7 - Wing FL - Scratch(es)



8 - Outer sill L - Deformed / Strained



9 - Door FL - Dent(s) and scratch(es)



10 - Outside rear-view mirror housing L - Broken



11 - Side wall RL - Dent(s) and scratch(es)



SIGNATURE

Expert

26/02/2026 13:27

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke.