



RENAULT CLIO: GD-602-KY

Vinnumber:	VF1RJA00X67891018	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N
First Registrationdate:	8/12/2021	Fiscalpower:	VP [5P] bva 6-140CH-5cv (bi-corps)
Expertise Mileage:	155739	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options


Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
GPS storage		Rear parking sensors	
GPS storage	HD	Seat cover lining	Lining Other
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Hankook: 60%	Fr.R.	Hankook: 55%
	Re.L.	Hankook: 30%	Re.R.	Hankook: 35%
Tyre profile depth FL				4.4
Tyre profile depth FR				4.5
Tyre profile depth RL				6.2
Tyre profile depth RR				6.0
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning



Armrest F M, Broken, Replace



Door panel RR, Scratch(es), Replace



Wheel cover RR, Broken, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Headlight R, Broken, Replace



Wing FR, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Paint



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Paint



Luggage compartment cover, Missing, Replace



Internal boot lining L, Broken, Replace



Bodywork, Not original part, Sticker removal small



Roof, Dent(s), Repair and paint (complete)

