

INSPECTION REPORT

End of contract

GENERAL INFO

File	313428
License plate	NT8635
Vehicle identification number	VXEVFAXKM7844327
Dossier	2021 055 038
Make	Opel Viv.Fg TD 150 3100 L3H1 E
Mileage	150793
First registration	12/10/2021
client availability date	21/05/2026
inspectionDate	01/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
654	Lettering Removal 15min	N
17	Bumper Front // Replace without painting	Y
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	Y
137	Bumper Rear // Replace without painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
234	Wing Front right // Repair & Painting	Y
239	Wing Front right / Inner Fender / Replace	N
294	Rear Loading Door Left // Repair & Painting	N
614	Front Left Door Interior Coating // Replace Completely	Y
624	Front Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Front // Replace without painting-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Door Front Right // Smart Repair Small-scratch



Bumper Rear // Replace without painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Front right // Repair & Painting-scratch + dent



Rear Loading Door Left // Repair & Painting-bad repair



Wing Front right / Inner Fender / Replace-cracked



Windshield // Replace-glass damage



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Lettering Removal 15min-Remainder stickers