

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	310487
License plate	2AEC934
Vehicle identification number	VF3MCYHZUMS018559
Dossier	2020302048
Make	Peugeot 5008 1.5BHdi 96kW Allu
Mileage	127003
First registration	05/03/2021
client availability date	20/04/2026
inspectionDate	24/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
18	Bumper Front / Spoiler / Replace	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
33	Front Bonnet // Repair & Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

## Damage Pictures



Rear Bonnet // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front / Spoiler / Replace-scratch




Bumper Front // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch




Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Rocker Panel Left // Smart Repair Medium-dent



Door Front Right // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Roof // Polish-Chemical reaction



Interior Cleaning // Small-stain



Seat Front Left / Bottom Coating / Replace-worn



Interior // Repair 1-bad position