



# CITROEN C3

## C3 PureTech 82 S&S BVM5 Live

VIN NO VF7SXHMRVKT720292

Registration Number FN809CQ



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	0	1	149855 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2023-03-20	87817	2020-01-19	France

### Inspection Report Summary

Customer	BCAuto Encheres	Mechanical Grade	
Inspection Date / Place	2025-12-16 / BCA MONTMARTIN	Cosmetic Grade	2

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1199
Engine Size	1.2	No of Doors	5
Family	Light Commercial Vehicle	Drive Train	Front
Charging Cables		No of Seats	2
NEDC CO2 Rating (g/km)	96	Seat Covering	
Engine Rating CV	4	Metalic Colour	
Accident Damage	No	Euro Emission	
First Registration / Construction Year	2020-01-19 / 1900-01-01	Arrival Date	2025-12-15
Service History	87817		

### Vehicle History & Documents

Service Book Available	Present	Previous Usage	Normal Use
Manufacturer Warrenty		Odometer Warranty	No
Next Service Mileage	km		

## Vehicle Remarketing Imagery

[Click Here For Larger Images](#)





## Equipment

---

Central locking	Cruise control	Power assisted steering	Radio
-----------------	----------------	-------------------------	-------

Front fog lamps

## Equipment Details

---

Presence Anti-Theft Lock Nut	Ok	Air Conditioning	Yes
------------------------------	----	------------------	-----

Seat Heating

No

## Wheels & Tyres

---

Left Rear Tyre Depth	2	Left Front Tyre Depth	2
----------------------	---	-----------------------	---


Right Rear Tyre Depth	2	Right Front Tyre Depth	2
-----------------------	---	------------------------	---

Tyres Comment


Ok

## Cosmetic Damage

10 Dommages




2 Dommages



Component	Damage	Comments
1 Hood	Bodywork / Dent / Hail Area	
2 Roof	Bodywork / Dent / Hail Area	
3 Floor Carpet	Interior / Dirty	
4 Rim / Front Right	Out of Bodywork / Scratch	
5 Rim / Front Left	Out of Bodywork / Scratch	
6 Rim / Back Left	Out of Bodywork / Scratch	
7 Rim / Back Right	Out of Bodywork / Scratch	
8 Tailgate	Bodywork / Dent / Dent	
9 Fender / Back Right	Paint / Scratch / Line	
10 Seat Cushion / Front Left	Interior / Stained	
11 Door / Front Left	Paint / Scratch / Line	
12 Door / Front Right	Bodywork / Dent / Dent	

## Vehicle Condition Imagery

[Click Here For Larger Images](#)



1. Hood  
Bodywork / Dent / Hail Area -



2. Roof  
Bodywork / Dent / Hail Area -




3. Floor Carpet  
Interior / Dirty -



4. Rim / Front Right  
Out of Bodywork / Scratch -



5. Rim / Front Left  
Out of Bodywork / Scratch -



6. Rim / Back Left  
Out of Bodywork / Scratch -



7. Rim / Back Right  
Out of Bodywork / Scratch -




8. Tailgate  
Bodywork / Dent / Dent -




9. Fender / Back Right  
Paint / Scratch / Line -



10. Seat Cushion / Front Left  
Interior / Stained -



11. Door / Front Left  
Paint / Scratch / Line -



12. Door / Front Right  
Bodywork / Dent / Dent -

## Mechanical Condition

### Levels

Oil level	✓	Level - Oil	✓
Coolant Fluid - Condition	✓	Coolant Fluid	✓
Brakes Fluid	✓		

### Engine

Cross Member	NA	Serpentine Belt	✓
Control Liquid Leak	✓		

### Equipments Test

Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	NA
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	Dump / Trail / Tail Gate Lift	NA
Electric Windows	✓	Audio Equipment	✓
Navigation System	NA	AC / Heating System	✓
Central Locking	✓		

### Dashboard Lights

ABS Warning Light	✓	Transmission Warning Light	NA
Diesel Particulate Filter Light	NA	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Service Light	✓
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Steering Fluid Level	NA
Level - Fuel / Battery	40		

### Hybrid/EV

Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		

### Comments

Comments

Bruit moteur

## Test Drive Inspection

### Test Drive

Engine functioning	<input checked="" type="checkbox"/>	Engine / Aux Belt / Pulley Noise	<input checked="" type="checkbox"/>
Steering Noise/Gripping	<input checked="" type="checkbox"/>	Vehicle Starts	<input checked="" type="checkbox"/>
Engine Power	<input checked="" type="checkbox"/>	Smoke Quantity	<input checked="" type="checkbox"/>
Transmission	<input checked="" type="checkbox"/>	Clutch Functioning	<input checked="" type="checkbox"/>
Brakes Functionning	<input checked="" type="checkbox"/>	Steering	<input checked="" type="checkbox"/>

 **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

 **Damages or malfunction detected that requires repairs by the buyer**

 **Not applicable**

 **Not tested**

### Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*