

APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name: HM Tongeren
Make: RENAULT
Model / version: KANGOO EXPRESS
Vin: VF1WF000268254133
Plate: 2BFD365
Mileage: 96946
First registration: 29/10/2021
Color:


ADDITIONAL INFORMATION




Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ✓

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ?

PICTURES





VIN INFORMATION

EQUIPMENT

Board computer:	✓	Central locking:	✓
Compressor:	✗	Cruise control:	✗
Gps:	✗	Power steering:	✓
Rear parking sensor:	✓	Repair kit:	✗
Front seats heated:	✗	Steering wheel:	✗
Electric windows:	✓	Climate control type:	
Headlighting type:	Halogen	Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Winter	Steel	✗
Front right	5 mm			Winter	Steel	✗
Rear left	5 mm			Winter	Steel	✗
Rear right	5 mm			Winter	Steel	✗

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Sliding door R	Dent(s)
2	Side wall RR	Dent(s) and scratch(es)
3	Side wall RL	Dent(s) and scratch(es)
4	Sliding door L	Grooved
5	Step L	Grooved


Total: 5

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
No damages present					

DAMAGES DETAILS

1 - Sliding door R - Dent(s)



2 - Side wall RR - Dent(s) and scratch(es)



3 - Side wall RL - Dent(s) and scratch(es)



4 - Sliding door L - Grooved



5 - Step L - Grooved



SIGNATURE

Expert

26/01/2026 13:21

Rm