



PEUGEOT 5008: FQ-419-DZ

Vinnumber:	VF3MCYHZRLL038684	Versionname:	PEUGEOT 5008 BlueHdi 130 S&S EAT8 ALLURE BUSINESS VP [5P] bva 8-130CH-6cv (SUV)
First Registrationdate:	2/06/2020	Fiscalpower:	
Expertise Mileage:	155809	Power Kw:	96
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	
Type of climate control	Autom climate control	Lining Other	
		Lining Semi-leather	

Tyres

225/55/18/102 V				
Winter tyres:	Fr.L.	Bridgestone: 45%	Fr.R.	Bridgestone: 45%
	Re.L.	Bridgestone: 30%	Re.R.	Bridgestone: 30%
Tyre profile depth FL				5.4
Tyre profile depth FR				5.2
Tyre profile depth RL				6.3
Tyre profile depth RR				6.1
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Dirty, Chemical cleaning			





Interior covering A pillar R, Tear, Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing RL, Scratch(es), Paint



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Side repeater L, Broken, Replace



Wing FL, Scratch(es), Polish



Door trim RL, Deformed / Strained, Replace



Bumper moulding F, Missing, Replace



Bumper spoiler F, Scratch(es), Acceptable



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Bad repair, Paint



Wing RR, Scratch(es), Paint



Wing trim RR, Unclashed, Dismount/Mount



Door trim FR, Deformed / Strained, Replace



Bumper corner RR, Scratch(es), Acceptable



Rear bulkhead lining, Scratch(es), Replace



Luggage compartment cover, Broken, Replace



Bumper moulding R, Scratch(es), Replace



Bumper corner RL, Scratch(es), Polish



Internal boot lining L, Scratch(es), Replace

