



PEUGEOT 3008: FT-135-SP

Vinnumber:	VF3MCYHZRLS217529	Versionname:	PEUGEOT 3008 BlueHdi 130 S&S EAT8 ACTIVE BUSINESS VP [5P] bva 8-130CH-7cv (SUV)
First Registrationdate:	27/10/2020	Fiscalpower:	
Expertise Mileage:	159894	Power Kw:	96
Bodytype:	SUV	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	215/65/17/103 V			
Summer tyres:	Fr.L.	Michelin: 60%	Fr.R.	Michelin: 60%
	Re.L.	Michelin: 45%	Re.R.	Michelin: 55%
Tyre profile depth FL				4.3
Tyre profile depth FR				4.2
Tyre profile depth RL				5.2
Tyre profile depth RR				4.6
Tyre size FL				215/65 R 17 103 V
Tyre size FR				215/65 R 17 103 V
Tyre size RL				215/65 R 17 103 V
Tyre size RR				215/65 R 17 103 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			





Malfunction indicator, Blinking, Check



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Paint



Door RL, Dent(s), Repair and paint (complete)



Roof pillar R, Dent(s), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Acceptable

