

# APPRAISAL REPORT



## IDENTIFICATION VEHICLE

Driver name: HM Tongeren  
Make: RENAULT  
Model / version: KANGOO EXPRESS  
Vin: VF1WF000368149004  
Plate: 2BFE045  
Mileage: 118740  
First registration: 29/10/2021  
Color:


## ADDITIONAL INFORMATION






Category:  
Transmission: Front  
Interior color:  
Metallic paint: ?  
Type of lining:  
Board computer reset: ✓

## DOCUMENTS

Certificate of conformity: ✓  
Registration certificate: ✓  
Registration certificate 2: ✓  
Insurance certificate: ?  
Maintenance book:  
Number of keys: 2  
Original key: ✓

## PICTURES





## VIN INFORMATION

### EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✗	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✗
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

### TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm			Winter		?
Front right	3 mm			Winter		?
Rear left	3 mm			Winter		?
Rear right	3 mm			Winter		?

#### DAMAGES SUMMARY

##### NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Inner door handle FL	Damaged
2	Step L	Grooved
3	Wing FR	Grooved
4	Door FL	Dent(s) and scratch(es)
5	Wing RL	Dent(s) and scratch(es)
6	Wing trim RL	Missing
7	Door FR	Dent(s) and scratch(es)

Total: 7

##### ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
No damages present					

#### DAMAGES DETAILS

1 - Inner door handle FL - Damaged



2 - Step L - Grooved



3 - Wing FR - Grooved



4 - Door FL - Dent(s) and scratch(es)



5 - Wing RL - Dent(s) and scratch(es)

---



6 - Wing trim RL - Missing

---



7 - Door FR - Dent(s) and scratch(es)

---



SIGNATURE

---

Expert

11/03/2026 13:16

C V