



RENAULT Master

2.3 DCI 135 PACK COMFORT L3H2

VIN	VF1MA000369212246
Registration	AABM423
Mileage	230,095 km
First registration date	7/18/2022
Body colour	White

INSPECTION DETAILS

Inspection date	9/3/2026 9:49:23 AM	Inspection address description	CarÉra
-----------------	---------------------	--------------------------------	--------

VEHICLE INFO

Make	RENAULT	Number of gears	6
Model	Master	Transmission	Front
Version	2.3 DCI 135 PACK COMFORT L3H2	Category	Light Commercial Vehicle
VIN	VF1MA000369212246	Body type	Truck
Registration	AABM423	Number of doors	4
First registration date	7/18/2022	Number of seats	3
Year of manufacture	2022	Interior colour	Black
Fuel type	Diesel	Body colour	White
Mileage	230,095 km	cc	2,299
Type of gearbox	Manual	kW	100

DOCUMENTS AND MAINTENANCE

Number of keys total	2	Type of Maintenance book	Maintenance book present
Registration certificate original	Yes	User's manual	Yes

EQUIPMENT ACCORDING TO INSPECTOR

Abnormal engine noises	No	Paint thickness Wing FR (µm)	110
Airco functioning	Yes	Paint thickness Wing RL (µm)	120
All seatbelts functional, damage free	All seatbelts OK	Paint thickness Wing RR (µm)	120
Cruise Control	Yes	Panoramic roof	No
Front parking sensors	No	Power steering functioning	Yes
Functioning headlight L	Yes	Radio multimedia	Yes
Functioning headlight R	Yes	Rear parking sensors	Yes
GPS	No	Rear view camera	No
Heat functioning without abnormalities	Yes	Seats F heated	No
Mirrors functioning	Yes	Test drive	Yes
Number of charging cables (normal)	0	Type of climate control	Manual climate control
Number of charging cables (rapid charge)	0	Type of GPS storage	N.A.
Paint thickness Bonnet (µm)	120	Type of headlighting	Headlighting Halogen

Paint thickness Door FL (µm)	110	Type of Lining	Lining fabrics
Paint thickness Door FR (µm)	100	Type of Tow bar	No Tow bar
Paint thickness Door RR (µm)	110	Vehicle running	Yes
Paint thickness Roof (µm)	100	Windows electric F	Yes
Paint thickness Trunk (µm)	110	Windows electric functioning	Yes
Paint thickness Wing FL (µm)	110		

TIRES

Mounted Tires

Location	Position	Tread	Manufacturer	Dimensions	Tire season	Type of rims	Runflat
Front	Left	6.0 mm	Continental	225/65 R 16 112 R	Summer	Steel	No
Front	Right	6.0 mm	Continental	225/65 R 16 112 R	Summer	Steel	No
Rear	Left	6.0 mm	Continental	225/65 R 16 112 R	Summer	Steel	No
Rear	Right	6.0 mm	Continental	225/65 R 16 112 R	Summer	Steel	No

DAMAGES

Interior



1 | Seat cover FL

Damage type	Burned
Severity	Unknown
Repair mode	Replace
Cause	Use/wear



4 | Rubber seal for boot lid

Damage type	Tearred
Severity	Unknown
Repair mode	Replace
Cause	Use/wear

Exterior



2 | Windscreen

Damage type	Stone chip(s)
Severity	Unknown
Repair mode	Windscreen repair
Cause	Use/wear



3 | Bumper F

Damage type	Dent(s)
Severity	Unknown
Repair mode	Smart repair
Cause	Use/wear



5 | Tailgate / Boot

Damage type	Dent(s) and scratch(es)
Severity	>50%, medium
Repair mode	Repair and paint (complete)
Cause	Use/wear



6 | Bodywork

Damage type	Dent(s)
Severity	Unknown
Repair mode	No repair
Cause	Use/wear





COMMENTS

i Inspector comments

Körben apró horpadások, karcok. Raktér részen kinyomódások.

Commercial photos

