



Hyundai Ioniq: G836RT

Vinnnummer:	KMHC851JFLU055139	Versionname:	Ioniq EV 100kW / 38kWh Comfort DCT
First Registrationdate:	21/11/2019	Fiscalpower:	
Expertise Mileage:	110002	Power Kw:	100
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	469
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment	
GPS		Central consol F	
Autom climate control		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Radio multimedia		Rear parking sensors	

Degree of wear

205/60/16/92 H				
Summer tyres:	Fr.L.	Michelin: 2,8 mm	Fr.R.	Michelin: 4,8 mm
	Re.L.	Michelin: 3,9 mm	Re.R.	Michelin: 3,3 mm
Tyre profile depth FL				2.8
Tyre profile depth FR				4.8
Tyre profile depth RL				3.9
Tyre profile depth RR				3.3
Tyre size FL				205/60 R 16 092 H
Tyre size FR				205/60 R 16 092 H
Tyre size RL				205/60 R 16 092 H
Tyre size RR				205/60 R 16 092 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Door panel FL, Scratch(es), Replace



Service, Maintenance, Execute



Interior, Dirty, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper spoiler F, Scratch(es), Repair and paint (complete)



Roof pillar R, Chemical polution, Polish



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Bumper R, Scratch(es), Polish



Roof, Rust, Repair and paint (complete)

