

# Renault

1.5 BLUE DCI 95 MAXI CONFORT

VIN: VF1WF000568254160



## Description

<b>Registration number</b> 2BFF250	<b>Registration date</b> 29/10/2021	<b>Odometer</b> 86531 km
<b>Color</b> -	<b>Year</b> -	<b>Upholstery</b> -
<b>Number of doors</b> 4	<b>Number of seats</b> -	<b>Generation</b> -
<b>Engine displacement</b> 1461 cc	<b>Max power</b> 70 KW	

## Statement details

**Inspection loc**  
PARC HÖDLMAYR TONGEREN

**Statement date**  
21/01/2026

**Inspection approval date**  
22/01/2026

## Control

**Engine start issue**  
No

**Is not roadworthy**  
No

## Defects & corrections

#	Element	Defect	Correction
001	Fabric door lining / Front Left	Non Compliant	Replace
002	Door / Front Left	Dent	Repair

<p>003</p>	<p>Bumper towing hook cover plate / Back Painted : No</p>	<p>Missing</p>	<p>Replace</p>
<p>004</p>	<p>Wing / Back Right</p>	<p>Dent</p>	<p>Repair</p>
<p>005</p>	<p>Wing moulding / Back Right</p>	<p>Missing</p>	<p>Replace</p>
<p>006</p>	<p>Seat complete / Front Right</p>	<p>Missing</p>	<p>Replace</p>
<p>007</p>	<p>Rear-view mirror / Right</p>	<p>Broken</p>	<p>Replace</p>
<p>008</p>	<p>Spare Key / -</p>	<p>Missing</p>	<p>Replace</p>

### Loose Items

- |  |  |  |
|--|--|--|
| <input type="checkbox"/> Toolkit                           | <input type="checkbox"/> Slow charging cable                 | <input type="checkbox"/> Quick charging cable                      |
| <input type="checkbox"/> Load cover                        | <input type="checkbox"/> Service book                        | <input type="checkbox"/> Warranty booklet                          |
| <input checked="" type="checkbox"/> Conformity certificate | <input checked="" type="checkbox"/> Registration certificate | <input checked="" type="checkbox"/> Registration certificate owner |
| <input type="checkbox"/> Locking wheel nut                 | <input type="checkbox"/> Card key                            | <input type="checkbox"/> Locking wheel nuts key                    |
| <input type="checkbox"/> Remote key                        | <input type="checkbox"/> Compressor tyre repair kit          | <input type="checkbox"/> Jack                                      |
| <input type="checkbox"/> Towing hook                       | <input type="checkbox"/> Hook /Hicth ball                    | <input type="checkbox"/> Spare Key                                 |
| <input type="checkbox"/> Cargo net                         | <input type="checkbox"/> Safety vest                         | <input type="checkbox"/> Tyre repair kit complete                  |
| <input type="checkbox"/> Security Kit                      | <input type="checkbox"/> Jack handle crank                   | <input type="checkbox"/> User manual                               |
| <input type="checkbox"/> Satellite navigation              | <input type="checkbox"/> In-car tools                        | <input type="checkbox"/> Rear parcel shelf                         |
| <input type="checkbox"/> Document holder                   | <input type="checkbox"/> Refill tyre repair kit              | <input checked="" type="checkbox"/> Spare wheel tyre               |
| <input type="checkbox"/> Charging cable bag                | <input type="checkbox"/> Remote control                      | <input type="checkbox"/> Triangle                                  |
| <input type="checkbox"/> First aid kit                     |  |  |

### Main set of tyres

<b>Front Left</b>	LAUFENN	195 / 65 / 15 / All	2 mm
<b>Front Right</b>	LAUFENN	195 / 65 / 15 / All	2 mm
<b>Back Left</b>	LAUFENN	195 / 65 / 15 / All	4 mm
<b>Back Right</b>	LAUFENN	195 / 65 / 15 / All	4 mm

### Comments

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation



Spare Tyre



Vin



