



status report

Report number:	0000000836170-EN968	Off. Mark :	TR-IB 90E
reference number:	30923695		

Vehicle Data

Hyundai Kona (OS)(2017->) Trend Elektro 2WD

Vehicle identification number .:	KMHK381HFMU125125	mileage read:	44211 km
First Registration / construction Year:	09.04.2021 / 2020	Inspection date/place:	11.04.2025 54439 Saarburg
Bodywork:	Cars	Body type:	hatchback
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	-	Displacement / power:	0 ccm / 100 kW (136 PS)
Drive type:	front-wheel drive	Paint:	Galaxy Grey / MIC
Type of paint:	Metallic	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	2026-05 / 2026-05
cushion type:	Substance	Service book available:	Yes
Interior Color:	Black	Maintained service book:	No
smoking vehicle:	No	Last service km / on the:	33794 / 2024-05-10
Vehicle roadworthy:	Yes	Submitted vehicle documents:	
State outside:		condition inside:	

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Mounted tires

	All weather tire	Aluminium original
Tyre / wheel type:		
1st axis - Left / states .	Uniroyal	215/55/R17/98W 6 mm
1st axis - right / states .	Uniroyal	215/55/R17/98W 6 mm
2nd axis - Left / states .	Uniroyal	215/55/R17/98W 6 mm
2nd axis - right / states .	Uniroyal	215/55/R17/98W 6 mm
Traffic Safety:	Roadworthy	

Unmounted tires

	Summer tires	Aluminium original
Tyre / wheel type:		
2nd axis - right / states .	-	-/-/- 6 mm
2nd axis - Left / states .	-	-/-/- 6 mm
1st axis - right / states .	-	-/-/- 6 mm
1st axis - Left / states .	-	-/-/- 6 mm
Traffic Safety:	Roadworthy	

Series

- | | |
|---|---|
| <ul style="list-style-type: none"> • 3rd brake light • Airbag passenger side • Airbag driver side • Anti-lock braking system (ABS) • Audio system: Radio RDS • Exterior mirror painted • Brake Assist • Rear Parking Sensors • Electr. Brake force distribution • Electron. Stability control (ESC) with brake assistant • Fahrassistenz-System: Aufmerksamkeits-Assistent • Driving assistance system: Autonomous emergency braking function including front collision warning (FCA) • Driver assistance system: hill start assist • Electric window rear • Handsfree Bluetooth | <ul style="list-style-type: none"> • 6 Lautsprecher • Airbag front passenger side can be switched off • Alarm system • Drive type: front-wheel drive • Outside mirror electr. adjustable and heated, both • Flashing light integrated in the exterior mirror • Roof rails • Automatic switch-on for driving lights / light sensor • Elektromotor 100 kW (cont. 26 kW) • Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System) • Driving assistance system: Autonomous emergency braking function including cyclist detection (FCA-Cyc.) • Driving assistance system: Autonomous emergency braking function including pedestrian detection (FCA-Ped.) • Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall) • Electric window lift at the front • Countersteering support (Vehicle Stability Management, VSM) |
|---|---|

- | | |
|---|--|
| <ul style="list-style-type: none"> • Gepäck-/Laderaumleuchte • Luggage compartment cover / roller blind • Getriebe für Elektrofahrzeug • Rear window heatable • Instrumente mit Farbdisplay 3,5 Zoll • Body: 5-door • Head airbag system • Kühlergrill Wagenfarbe • Steering wheel (leather) with multifunction • Steering wheel with paddle shifters • Headlamp leveling • Center armrest front with compartment • Parking brake electric (EPB) • Radstand 2600 mm • Tire repair kit • Backup camera • Shift / selector lever handle leather • Side airbag in front • Seat front left height adjustable • Heated seats in the front • Sonderlackierung Galaxy Gray Metallic • Start-stop button • Daytime running light LED • Trend-Paket • Türgriffe innen verchromt • Glazed tinted • Central locking with remote control | <ul style="list-style-type: none"> • Luggage net in the luggage / loading space • Cruise control system (tempomat) with distance control ACC • Cup holder in front • Tweeter • Isofix seats for child seat • Climate • Headrests adjustable at the back • Lumbar support seat front left, electr. adjustable • Lenkrad heizbar • Reading light • LM-Felgen 7x17 • Notladekabel (ICCB) • Radio reception digital (DAB +) • Tires 215/55 R17 ..V • Tire pressure monitoring system • Rear seat back divided / foldable • Window fogging detection / control • Power steering • Seat cover / upholstery: fabric • Smart key • Sun visors with mirror (illuminated) • Start / Stop system • Color touchscreen display (7.0 inches) • Door handles outside body color • USB port + AUX-IN port • Immobilizer (electronic) |
|---|--|

Special Features

- | | |
|---|--|
| <ul style="list-style-type: none"> • Mica finish / mineral effect finish | <ul style="list-style-type: none"> • GPS package
Sound-System KRELL, 8 speakers, subwoofer, Smartphone Schnittstelle (Apple CarPlay & Android Auto), navigation system, Service system: Remote Services (Blue Link), Touchscreen color display (10.25 inch) |
|---|--|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General exam

test drive:

Subfloor Inspection:

Mileage plausible:

reference:

Note Road Safe:

Accident claims investigation

Rep. Predamages / -height gross:

Layers of paint thickness
measurement:

Existing collision damage:

reference:

Overview of technical examination

Air conditioning:	Examined limited	✗	Lighting system:	examined limited	✗
Sunroof / convertible:	unavailable	✗	Seat heating:	Examined limited	✗

Damage



Others

	Component	Damage	Rep kind
1.	Verlust der Herstellergarantie und jeglicher Kulanz möglich.		
2.	Tire-fit filler	Missing	Replace
3.	Tire-fit compressor	Missing	Replace

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .

Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside




instrument cluster



mileage




center console



key



key



Service book / proof



Others



engine compartment



rim



tires



tires



tires



Hüsches Gruppe®
Die Gutachter



tires