



# CITROEN C4

## C4 Spacetourer BlueHDi 130 S&S BVM6 Business



VIN NO VF73AYHZPKJ757555  
Registration Number FK957XF

MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2019-10-16

Odometer Reading

226001 km

Country First Registered



### Inspection Report Summary

Customer	BCA Auto Encheres	Mechanical Grade	
Inspection Date / Place	2026-04-20 / BCA BOUCHAIN	Cosmetic Grade	3


### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Light Grey	Engine Size (cc)	1499
Engine Size	1.5	No of Doors	5
Body Type	MPV	Drive Train	Front
Charging Cables		No of Seats	2
WLTP CO2 Emissions		Seat Covering	
Engine Rating CV	6	Metalic Colour	
Accident Damage	No	Euro Emission	
First Registration / Construction Year	2019-10-16 / 1900-01-01	Arrival Date	2026-04-17

### Vehicle History & Documents

Service Book Available	Missing	Previous Usage	Normal Use
Manufacturer Warranty		Odometer Warranty	No
Next Service Mileage	km		





## Equipment

---

Central locking	Radio	Alloys wheels	Front fog lamps
Roof rails	Electrically folding wing mirrors	Rear parking sensors	Cruise control
Power assisted steering	Satellite navigation		

## Equipment Details

---

Presence Anti-Theft Lock Nut	Ok	Air Conditioning	Yes
Seat Heating	No		


## Wheels & Tyres

---


Left Rear Tyre Depth	5	Left Front Tyre Depth	2
Right Rear Tyre Depth	5	Right Front Tyre Depth	2

## Cosmetic Damage

17 identified damages



0 identified damages



Component	Damage	Comments
1 Corner Bumper / Back Left	Paint / Scratch / Scuff	
2 Hood	Paint / Stone Chip	
3 Corner Bumper / Back Right	Paint / Scratch / Scuff	
4 Fender / Back Left	Paint / Scratch / Scuff	
5 Bumper / Back	Paint / Scratch / Scuff	
6 Bumper / Front	Paint / Scratch / Scuff	
7 Door / Back Right	Paint / Scratch / Scuff	
8 Fender / Front Right	Paint / Scratch / Scuff	
9 Door / Back Left	Paint / Stone Chip	
10 Rim / Back Left	Out of Bodywork / Scratch	
11 Door / Back Left	Paint / Scratch / Scuff	


12	Door / Front Left	Paint / Stone Chip
13	Fender / Front Left	Bodywork / Dent / Dent
14	Door / Back Right	Paint / Stone Chip
15	Rim / Back Right	Out of Bodywork / Scratch
16	Rim / Front Right	Out of Bodywork / Scratch
17	Rim / Front Left	Out of Bodywork / Scratch




1. Corner Bumper / Back Left  
Paint / Scratch / Scuff -



2. Hood  
Paint / Stone Chip -



3. Corner Bumper / Back Right  
Paint / Scratch / Scuff -



4. Fender / Back Left  
Paint / Scratch / Scuff -




5. Bumper / Back  
Paint / Scratch / Scuff -



6. Bumper / Front  
Paint / Scratch / Scuff -



7. Door / Back Right  
Paint / Scratch / Scuff -




8. Fender / Front Right  
Paint / Scratch / Scuff -



9. Door / Back Left  
Paint / Stone Chip -



10. Rim / Back Left  
Out of Bodywork / Scratch -



11. Door / Back Left  
Paint / Scratch / Scuff -



12. Door / Front Left  
Paint / Stone Chip -



13. Fender / Front Left  
Bodywork / Dent / Dent -



14. Door / Back Right  
Paint / Stone Chip -



15. Rim / Back Right  
Out of Bodywork / Scratch -



16. Rim / Front Right  
Out of Bodywork / Scratch -



17. Rim / Front Left  
Out of Bodywork / Scratch -

## Mechanical Condition

Levels			
Oil Condition	✓	Level - Oil	✓
Coolant Fluid - Condition	✓	Coolant Fluid level	✓
Brakes Fluid	✓		
Engine			
Cross Member	✓	Serpentine Belt	✓
Control Liquid Leak	✓		
Equipments Test			
Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	✓
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	Dump / Trail / Tail Gate Lift	NA
Electric Windows	✓	Audio Equipment	✓
Navigation System	✓	AC / Heating System	✓
Central Locking	✓		
Dashboard Lights			
ABS Warning Light	✓	Transmission Warning Light	✓
Diesel Particulate Filter Light	✓	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Service Light	✓
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Steering Fluid Level	NA
Level - Fuel / Battery	15		
Hybrid/EV			
Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		

## Test Drive Inspection

---

### Test Drive

Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	✓
Transmission	✓	Clutch Functioning	✓
Brakes Functioning	✓	Steering	✓

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

! *Damages or malfunction detected that requires repairs by the buyer*

NA *Not applicable*

☐ *Not tested*

### Disclaimer Section

---

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*