



Renault Megane

1.6 E-Tech plug-in hybrid 160 Zen

VIN NO VF1RFB00068522251

Registration Number DJ93944



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2022-06-30

Odometer Reading



141988 km

Country First Registered



Denmark

Inspection Report Summary

Customer	BCA Vejle	Mechanical Grade	
Inspection Date / Place	2026-08-10 / Auktionsvej 8 Vers. 2	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying Net
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Gearbox Type	Automatic
Colour	Black	No of Doors	5
Engine Size (cc)	1598	Seat Covering	
Body Type	Stationwagon / Estate	Drive Train	Front
WLTP CO2 Emissions		No of Seats	5
Battery State of Health		Charging Cables	OUC + Type 2
Service History	Present	Arrival Date	2026-07-22

Vehicle History & Documents

Service Book Available	Present	Previous Usage	Normal Use
Next Service Mileage	km	Imported	No


Vehicle Remarketing Imagery



Vehicle Remarketing Imagery



Vehicle Remarketing Imagery





Equipment

Cruise control

Front parking sensors

Rear parking sensors

Satellite navigation

Tow ball

Wheels & Tyres

Mounted Tires

Tyre / Wheel Type

//R / 4 mm


//R / 4 mm

//R / 6 mm


//R / 6 mm

Cosmetic Damage

7 identified damages




0 identified damages




Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Door / Back Right	Paint / Scratch / Scuff	
3	Door / Front Left	Paint / Chipping	
4	Bumper / Front	Paint / Chipping	
5	Bumper / Back	Paint / Scratch / Scuff	
6	Hood	Paint / Chipping	
7	Door / Front Right	Paint / Chipping	


Vehicle Condition Imagery




1. Windshield / Front
Glass Break / Impact -



2. Door / Back Right
Paint / Scratch / Scuff -



3. Door / Front Left
Paint / Chipping -




4. Bumper / Front
Paint / Chipping -



5. Bumper / Back
Paint / Scratch / Scuff -



6. Hood
Paint / Chipping -



7. Door / Front Right
Paint / Chipping -

Mechanical Condition

Control Lights

No Dashboard Lights



Engine

Engine Functioning



Vehicle Start - up



Other Checks

Clutch Functioning



Steering Functioning



Equipments Test

Audio Equipment



Electric Windows



Main & Spare Keys
Functioning



AC/Heating System



Parking Sensors/Cameras
Functioning



Navigation Equipment



Central Locking TD



Hybrid/EV

Charge Port Condition



Charge Lead Condition



Test Drive Inspection

Other Checks

Steering Noise



Brake System Functioning



Gears Functioning



Engine

Power Loss



Excessive Fume
Quantity/Colour



Engine Noise



 **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

 **Damages or malfunction detected that requires repairs by the buyer**

 **Not applicable**

 **Not tested**