

Renault

1.5 BLUE DCI 80 GRAND CONFORT

VIN: VF1WF000568254028



Description

Registration number	Registration date	Odometer
2BED143	19/10/2021	178353 km
Color	Year	Upholstery
-	-	-
Number of doors	Number of seats	Generation
4	-	-
Engine displacement	Max power	
1461	59 KW	

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	15/07/2026	16/07/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Wheel trim / Front Right Rim/Tyre diameter : 15 "	Broken	Replace
			
002	Wheel trim / Back Right Rim/Tyre diameter : 15 "	Missing	Replace

			
003	Windscreen / -	Chip	Replace
			
004	Bonnet / -	Dent	Acceptable
			
005	Sill cover / Front Right Painted : No	Missing	Replace
			
006	Seat / Front Left Trim material : Fabric	Dirty	Cleaning
			
007	Wing / Back Left	Dent	Repair
			
008	Fabric door lining / Back Left	Broken	Replace



009

Roof / -

Sunroof : No

Dent

Repair



010

Door / Back Left

Windowed : No

Dent

Repair



011

Door / Back Right

Windowed : No

Dent

Repair



012

Wing / Back Right

Dent

Repair



013

Door / Back Right

Dent

Repair



014


Seat back / Front Right

Trim material : Fabric

Burn mark

Smart repair



015	Bumper / Back Painted : No	Non Compliant	Refit
			

Loose Items

- ☐ Rear parcel shelf
- ☐ Tyre repair kit complete
- ☐ Document holder
- ☒ Registration certificate owner
- ☐ Toolkit
- ☐ Jack handle crank
- ☐ Slow charging cable (Type 2, Mode 2)
- ☐ Charging cable bag
- ☒ Spare Key
- ☐ Service book
- ☐ Towing hook
- ☐ Cargo net
- ☐ Remote key
- ☐ Security Kit
- ☒ Triangle
- ☐ Warranty booklet
- ☐ Hook /Hicth ball
- ☐ Card key
- ☐ Locking wheel nuts key
- ☒ Conformity certificate
- ☒ Spare wheel tyre
- ☐ Quick charging cable (Type 2, Mode 3)
- ☐ Safety vest
- ☐ Remote control
- ☐ Compressor tyre repair kit
- ☒ First aid kit
- ☐ User manual
- ☒ Jack
- ☐ Load cover
- ☐ Refill tyre repair kit
- ☒ Registration certificate
- ☐ Satellite navigation
- ☐ In-car tools
- ☐ Locking wheel nut

Main set of tyres

Front Left	FULDA	195 / 65 / 15 / Winter	5 mm
Front Right	FULDA	195 / 65 / 15 / Winter	5 mm
Back Left	FULDA	195 / 65 / 15 / Winter	6 mm
Back Right	FULDA	195 / 65 / 15 / Winter	6 mm

Comments

Expertise onder voorbehoud

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment




Front right



Odometer



Navigation



Spare Tyre




Vin



Other



Other



Other



Wheel trim / Front Right / Broken



Wheel trim / Front Right / Broken



Wheel trim / Back Right / Missing



Windscreen / - / Chip



Windscreen / - / Chip



Bonnet / - / Dent



Sill cover / Front Right / Missing



Seat / Front Left / Dirty



Wing / Back Left / Dent



Wing / Back Left / Dent



Fabric door lining / Back Left / Broken



Roof / - / Dent



Roof / - / Dent



Roof / - / Dent



Door / Back Left / Dent



Door / Back Left / Dent



Door / Back Left / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Seat back / Front Right / Burn mark



Seat back / Front Right / Burn mark

