



SKODA OCTAVIA COMBI: EP-781-ZZ

Vinnumber:	TMBJG7NE2J0103323	Versionname:	SKODA OCTAVIA COMBI 1.6 TDI 116 Business (TRANSFO) VF [5P] 5-116CH-6cv (break VU)
First Registrationdate:	23/08/2017	Fiscalpower:	
Expertise Mileage:	174089	Power Kw:	85
Bodytype:	Break	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Aluminium		
Category:	VS		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

205/55/16/91 H				
Summer tyres:	Fr.L.	Bridgestone: 75%	Fr.R.	Bridgestone: 75%
	Re.L.	Bridgestone: 70%	Re.R.	Bridgestone: 85%
Tyre profile depth FL				3.2
Tyre profile depth FR				3.4
Tyre profile depth RL				3.8
Tyre profile depth RR				2.4
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Stain, Cleaning			





Armrest F M, Burned, Replace



Tyre FL, Out of tolerance, Replace



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Wing FL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Door RL, Dent(s) and scratch(es), Replace and paint



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Bad repair, Paint



Headlight R, Broken, Replace



Bumper F, Deformed / Strained, Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Paint



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Rear bulkhead lining, Unclashed, Dismount/Mount



Boot lid covering R, Scratch(es), Replace



Bumper R, Deformed / Strained, Replace and paint



Rear light R, Scratch(es), Replace



Bumper spoiler Rear, Scratch(es), Replace



Roof, Dent(s), Repair and paint (complete)

