

Renault

1.5 BLUE DCI 95 MAXI CONFORT

VIN: VF1WF000X68254218



Description

Registration number 2BKC330	Registration date 15/12/2021	Odometer 70318 km
Color -	Year -	Upholstery -
Number of doors 4	Number of seats -	Generation -
Engine displacement 1461 cc	Max power 70 KW	

Statement details

Inspection loc
PARC HÖDLMAYR TONGEREN

Statement date
18/02/2026

Inspection approval date
19/02/2026

Control



Engine start issue
No

Is not roadworthy
No

Defects & corrections

#	Element	Defect	Correction
001	Dashboard trim / -	Punctured	Acceptable
002	Roof / -	Rust	Repair

	 		
003	Interior tailgate lining / Back Left	Broken	Replace
	 		
004	Wheel hub cap / Front Right	Missing	Replace
	 		
005	Wheel hub cap / Front Left	Missing	Replace
	 		
006	Windscreen / -	Chip	Acceptable
			
007	Rear-view mirror / Left	Scratched	Acceptable
			
008	Rear-view mirror / Right	Scratched	Acceptable
			

009	Bumper / Front Painted : No	Broken	Replace
			
010	Wing / Front Right	Punctured	Replace
			
011	Headlight / Front Left	Scratched	Replace
			
012	Wing / Front Left	Broken	Replace
			
013	Door / Front Left	Dent	Repair
			
014	Door sill / Front Left	Scratched	Acceptable
			
015	Door handle trim / Front Left	Broken	Replace

			
016	Door / Back Left	Dent	Repair
			
017	Wing / Back Left	Dent	Repair
			
018	Bumper towing hook cover plate / Back Painted : No	Missing	Replace
			
019	Bumper / Back Painted : No	Dent	Repair
			
020	Door / Back Left Windowed : Yes	Scratched	Acceptable
			
021	Window / Left Tinted window : No / Fixed window Pane : Yes	Scratched	Replace
			

022	Rear light (wing) / Back Right	Broken	Replace
023	Wing / Back Right	Dent	Repair
024	Wing moulding / Back Right Chromed : No	Missing	Replace
025	Door / Back Right	Dent	Repair
026	Door moulding / Right Painted : No	Broken	Replace
027	Door / Front Right	Dent	Repair

Loose Items

Rear parcel shelf

Remote key

Remote control

- Tyre repair kit complete
- Document holder
- Registration certificate owner
- Toolkit
- Jack handle crank
- Slow charging cable
- Charging cable bag
- Spare Key
- Service book
- Towing hook
- Cargo net

- Security Kit
- Triangle
- Warranty booklet
- Hook /Hitch ball
- Card key
- Locking wheel nuts key
- Conformity certificate
- Spare wheel tyre
- Quick charging cable
- Safety vest

- Compressor tyre repair kit
- First aid kit
- User manual
- Jack
- Load cover
- Refill tyre repair kit
- Registration certificate
- Satellite navigation
- In-car tools
- Locking wheel nut

Main set of tyres

Front Left	GOODYEAR	195 / 65 / 15 / All	5 mm
Front Right	GOODYEAR	195 / 65 / 15 / All	5 mm
Back Left	GOODYEAR	195 / 65 / 15 / All	5 mm
Back Right	GOODYEAR	195 / 65 / 15 / All	5 mm

Comments

Pictures



Front left




Rear left



Boot opened




Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer






Navigation



Spare Tyre



Vin





Rear-view mirror / Left / Scratched



Rear-view mirror / Right / Scratched



Bumper / Front / Broken



Bumper / Front / Broken



Bumper / Front / Broken



Bumper / Front / Broken



Bumper / Front / Broken



Wing / Front Right / Punctured



Wing / Front Right / Punctured



Headlight / Front Left / Scratched



Headlight / Front Left / Scratched



Wing / Front Left / Broken



Wing / Front Left / Broken



Wing / Front Left / Broken




Wing / Front Left / Broken



Door / Front Left / Dent



Door / Front Left / Dent



Door / Front Left / Dent



Door sill / Front Left / Scratched




Door handle trim / Front Left / Broken



Door handle trim / Front Left / Broken



Door handle trim / Front Left / Broken



Door / Back Left / Dent



Door / Back Left / Dent




Door / Back Left / Dent



Door / Back Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Bumper towing hook cover plate / Back / Missing



Bumper towing hook cover plate / Back / Missing



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Door / Back Left / Scratched



Window / Left / Scratched



Window / Left / Scratched



Window / Left / Scratched



Rear light (wing) / Back Right / Broken



Rear light (wing) / Back Right / Broken



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing moulding / Back Right / Missing



Wing moulding / Back Right / Missing



Door / Back Right / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Door moulding / Right / Broken



Door moulding / Right / Broken



Door / Front Right / Dent



Door / Front Right / Dent