




Vehicle details

VIN	VF1RFB002 66828055	Mileage	170 413 km	Engine (Fuel) Type	Petrol
Licence Plate	GC626HP	Registration date	12/10/2021	Engine size	1461
Brand	RENAULT	Fuel level	25 %	Transmission	Automatic
Model	Megane4Estate-2016	Car type	PC	Gears	7
Body Type	Estate	Number of seats	-	Condition of the car	Compliant
Doors	5	Exterior Color	Noir		

Inspection Details

Inspection date	04/09/2026	Inspection loc.	CAT AMBERIEU	Fleet owner	ARVAL FR
-----------------	------------	-----------------	--------------	-------------	----------



Other technical information

Metallic paint	Refill emergency kit	✓	User manual	✓
Running car - OK -	Emergency compressor kit	✗	Warranty booklet	✗
Operating engine - OK -			Log books	✗
Working battery - OK -			Spare key	✗
Working gearbox - OK -				

Options / Equipment

Tyres

Michelin 205/55/16 V All seasons 5.5 mm	Michelin 205/55/16 V All seasons 5.5 mm
Michelin 205/55/16 V All seasons 7.0 mm	Michelin 205/55/16 V All seasons 6.5 mm

Damages

1		Part	Floor mat	2		Part	Exterior door mirror shell
		Position	Front left			Position	Right
		Damages	Perforated			Damages	Scratched
		Severity	-			Severity	Length (cm) > 4
		Repair mode	For info			Repair mode	Repair



3		Part Position Damages Severity Repair mode	Wiper arm nut trim Back Missing - Replace
4		Part Position Damages Severity Repair mode	Warranty booklet - Missing - For info
5		Part Position Damages Severity Repair mode	Spare key - Missing - For info
6		Part Position Damages Severity Repair mode	Emergency compressor kit - Missing - Lumpsum replacement
7		Part Position Damages Severity Repair mode	Log books - Missing - For info
8		Part Position Damages Severity Repair mode	Tyre Front left Cut - Replace
9		Part Position Damages Severity Repair mode	Tyre Back right Cut - Replace
10		Part Position Damages Severity Repair mode	Wing Back right Dented - Repair
11		Part Position Damages Severity Repair mode	Door Back right Dented - For info
12		Part Position Damages Severity Repair mode	Roof - Chemical deposit - Repair
13		Part Position Damages Severity Repair mode	Bumper Front Dented - Repair
14		Part Position Damages Severity Repair mode	Bumper obturator Front Missing - Replace
15		Part Position Damages Severity Repair mode	Rear parking sensor Front Dented - For info
16		Part Position Damages Severity Repair mode	Bumper grille Front right Scratched - For info
17		Part Position Damages Severity Repair mode	Registration plates Front Broken - Lumpsum replacement
18		Part Position Damages Severity Repair mode	Bonnet - Dented - Repair



19



Part	Sill
Position	Left
Damages	Scratched
Severity	-
Repair mode	For info

20



Part	Wing
Position	Back left
Damages	Improper repair
Severity	-
Repair mode	Repair

21



Part	Bumper
Position	Back
Damages	Dented
Severity	-
Repair mode	Replace

22



Part	Spoiler
Position	Back
Damages	Misaligned
Severity	-
Repair mode	Adjust

23



Part	Roof post A/B/C
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info