

K-716-FR **DS Automobiles 3 Crossback E-Tense Business, Dec-20, 127,748 km**



Initial registration	28-12-2020
Initial Dutch Registration	28-12-2020
European Type Approval	e2*2007/46*0639*09
Mileage reading / hour counter reading	127,748 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	1498 kg
Doors	5
Power capacity	100 kW
Emission code / Energy label	Z
Wheelbase	256
Loading space	
Load capacity	
RDW details	
Battery capacity	50 kWh
Range	320 km
Battery health	92 %
Charging cables type	2
AC/DC	
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Black
Country of registration	The Netherlands
Indicative catalog price	€44,589

Accessories fitted to vehicles

 Rear view camera	 Central locking remote control	 Navigation
 Adaptive cruise control	 Electric windows front + rear	 Parking sensors front + rear
 Apple Carpl./Android Car	 Semi-leather upholstery	 Rain sensor
 Audio installation	 LED lighting	 Power steering
 Automatic air conditioning ECC	 Alloy rims	 Heated front seats
 Bluetooth telephone connection	 Metallic paint	



Comments

No remarks

Vehicle state

MOT due date	28-12-2026	Cambelt replaced	Charging cable for charging station 2 (7	Not present
--------------	------------	------------------	--	-------------

Maintenance history	Not present	Number of keys	2	pins)	Charging cable for charging station 1 (5	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	pins)	Charging cable for plug connection	Not present
		Vehicle location	At Barneveld location		Wheel locks	Not present

Technical state			
	Group	Observations	Comments
No information			
Comments			
No remarks			

Tyres			
Rim size	17"		
Wheel	Brand	Type	Tread depth
Front wheel left	Goodyear	All Season tyre	4 mm
Front wheel right	Goodyear	All Season tyre	2 mm
Rear wheel left	Goodyear	All Season tyre	5 mm
Rear wheel right	Goodyear	All Season tyre	4 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			


Bodywork inspection		
Incident	Component	Observations
Acceptable damage		
1	Exterior	car wash scratches
	Front	stone impact
	A-post right	little scratch(es)
Unacceptable damage		
2	Front door left	little scratch(es)
3	Front wing left	little scratch(es)
4	Wheel rim left-front	scuffed
5	Front bumper	little scratch(es)
6	Front door right	scratch/dent
7	Rear door right	little scratch(es)
8	Rear wing right	little scratch(es)
9	Rear bumper	little scratch(es)



10



11



12




13



14



15



16



17



Boot lid

bird waste

Rear wing left

little scratch(es)

Rear door left

scratch(es) , deukje

Roof

little scratch(es), hagelschade <10 deukjes

Front seat left

crack

A-post left

little scratch(es)

Front screen

chip(s)

Exterior

wrap advertising

Comments

No remarks