

Vehicle details

VIN	VF1WF0008 68525132	Mileage	108 380 km	Engine (Fuel) Type	Diesel
Licence Plate	GD613RM	Registration date	20/12/2021	Engine size	1461
Brand	RENAULT	Fuel level	25 %	Transmission	Manual
Model	Express-1986	Car type	LCV	Gears	6
Body Type	Panel van	Number of seats	-	Condition of the car	Compliant
Doors	4	Exterior Color	Blanc		

Inspection Details

Inspection date	28/08/2026	Inspection loc.	CAT AMBERIEU	Fleet owner	ARVAL FR
-----------------	------------	-----------------	--------------	-------------	----------





Other technical information

Metallic paint	Spare wheel (wheel & tyre)	✓	User manual	✓
Running car - OK -			Warranty booklet	✗
Operating engine - OK -			Log books	✗
Working battery - OK -			Spare key	✗
Working gearbox - OK -				

Options / Equipment

Tyres

Michelin 195/65/15 H Summer 6.0 mm		Michelin 195/65/15 H Summer 6.0 mm	
Michelin 195/65/15 H Summer 6.0 mm		Michelin 195/65/15 H Summer 6.0 mm	

Damages

1		Part	Air vent	2		Part	Air vent
		Position	Front			Position	Front
		Damages	Broken			Damages	Broken
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	Replace

3		Part GPS Navigation SD card Position - Damages Missing Severity - Repair mode Replace	4		Part Fabric seat Position Front left Damages Perforated Severity - Repair mode Smart Repair
5		Part Fabric seat Position Front right Damages Stained/dirty Severity - Repair mode Cleaning	6		Part Single lock barrel Position Side right Damages Missing Severity - Repair mode Lumpsum repair
7		Part Door moulding Position Side right Damages Dented Severity - Repair mode For info	8		Part Warranty booklet Position - Damages Missing Severity - Repair mode For info
9		Part Spare key Position - Damages Missing Severity - Repair mode For info	10		Part Log books Position - Damages Missing Severity - Repair mode For info
11		Part Exterior door mirror shell Position Right Damages Scratched Severity - Repair mode For info	12		Part Wheelcap 15" Position Front right Damages Missing Severity - Repair mode Replace
13		Part Steel wheel 15" Position Front right Damages Dented Severity - Repair mode For info	14		Part Wheelcap 15" Position Front left Damages Missing Severity - Repair mode Replace
15		Part Wheelcap 15" Position Back left Damages Missing Severity - Repair mode Replace	16		Part Steel wheel 15" Position Back left Damages Dented Severity - Repair mode For info
17		Part Wheelcap 15" Position Back right Damages Missing Severity - Repair mode Replace	18		Part Shutter Position Front left Damages Missing Severity - Repair mode Replace

19



Part

Position

Damages

Severity

Repair mode

Shutter

Back left

Missing

-

Replace

20



Part

Position

Damages

Severity

Repair mode

Shutter

Back right

Missing

-

Replace

21



Part

Position

Damages

Severity

Repair mode

Shutter

Front right

Missing

-

Replace

22



Part

Position

Damages

Severity

Repair mode

Roof

-

Dented

-

Repair

23



Part

Position

Damages

Severity

Repair mode

Side panel

Right

Improper repair

-

Repair

24



Part

Position

Damages

Severity

Repair mode

Door

Side right

Perforated

-

Repair

25



Part

Position

Damages

Severity

Repair mode

Door

Front right

Dented

-

Repair

26



Part

Position

Damages

Severity

Repair mode

Exterior door mirror shell


Left

Scratched

-

For info

27



Part

Position

Damages

Severity

Repair mode

Electric door mirror

Left

Broken

-

Replace

28



Part

Position

Damages

Severity

Repair mode

Door

Front left

Dented

-

Repair

29



Part

Position

Damages

Severity

Repair mode

Side panel

Left

Scratched

Length (cm) > 4

Repair

30



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Dented

-

For info

31



Part

Position

Damages

Severity

Repair mode

Door

Back left

Dented

-

Repair

32



Part

Position

Damages

Severity

Repair mode

Door

Back right

Dented

-

For info

33



Part

Position

Damages

Severity

Repair mode

Windscreen

-

Glazing impact

Number > 3

Replace

34



Part

Position

Damages

Severity

Repair mode

Jack

-

Clear

-

For info