

Renault

1.5 BLUE DCI 95 MAXI CONFORT

VIN: VF1WF000X67081127



Description

| | | |
|---------------------------------------|--|-----------------------------|
| Registration number 2ARJ265 | Registration date 21/06/2021 | Odometer 77707 km |
| Color - | Year 2007 | Upholstery - |
| Number of doors 4 | Number of seats - | Generation - |
| Engine displacement 1461 cc | Max power 70 KW | |

Statement details

Inspection loc
PARC HÖDLMAYR TONGEREN

Statement date
12/02/2026

Inspection approval date
13/02/2026

Control

Engine start issue
No

Is not roadworthy
No

Defects & corrections

| # | Element | Defect | Correction |
|-----|-----------------------------|-----------|------------|
| 001 | Dashboard trim / - | Punctured | Acceptable |
| | | | |
| 002 | Gear lever console trim / - | Tear | Acceptable |



003

Door interior trim / Front Left

Punctured

Replace



004

Interior tailgate lining / Back Left

Broken

Replace




005

Roof / -

Rust

Repair



006

Wheel hub cap / Front Left

Missing

Replace



007

Rear-view mirror / Left

Scratched

Acceptable




008

Rear-view mirror / Right

Broken

Replace



| | | | |
|---|--------------------------------|-----------|--------------|
| 009 | Bonnet / - 1 | Dent | Smart repair |
|  | | | |
| 010 | Headlight / Front Right | Scratched | Replace |
|  | | | |
| 011 | Bumper / Front Painted : No | Broken | Replace |
|  | | | |
| 012 | Headlight / Front Left | Scratched | Polishing |
|  | | | |
| 013 | Wing / Front Left | Scratched | Painting |
|  | | | |
| 014 | Wheel arch trim / Front Left | Broken | Replace |
|  | | | |
| 015 | Door / Front Left | Dent | Repair |



016

Doorframe seal / Front Left

Tear

Replace



017

Door sill / Front Left

Scratched

Acceptable



018

Wing / Back Left

Dent

Replace



019

Rear light (wing) / Back Left

Broken

Replace



020

Fog lamp / Back Left

Broken

Replace



021

Bumper / Back
Painted : No

Broken

Replace

| | | | | |
|-----|---|---|--|---|
| |  |  |  | |
| 022 | Door / Back Left ² Windowed : Yes | Scratched | | Acceptable |
| |  | | | |
| 023 | Rear light (wing) / Back Right | Broken | | Replace |
| |  |  | | |
| 024 | Wing / Back Right | Dent | | Repair |
| |  |  |  | |
| 025 | Sill / Right | Dent | | Repair |
| |  |  |  |  |
| 026 | Door / Back Right Windowed : Yes | Dent | | Repair |
| |  |  |  | |
| 027 | Door moulding / Right Painted : No | Scratched | | Replace |



028 Door moulding / Front Right Missing Replace
Painted : No



029 Door / Front Right Dent Repair



¹ 4x
² +deuk

Loose Items

- | | | |
|--|--|--|
| <input type="checkbox"/> Rear parcel shelf | <input checked="" type="checkbox"/> Remote key | <input type="checkbox"/> Remote control |
| <input type="checkbox"/> Tyre repair kit complete | <input type="checkbox"/> Security Kit | <input type="checkbox"/> Compressor tyre repair kit |
| <input checked="" type="checkbox"/> Document holder | <input type="checkbox"/> Triangle | <input type="checkbox"/> First aid kit |
| <input checked="" type="checkbox"/> Registration certificate owner | <input checked="" type="checkbox"/> Warranty booklet | <input checked="" type="checkbox"/> User manual |
| <input type="checkbox"/> Toolkit | <input type="checkbox"/> Hook /Hicth ball | <input type="checkbox"/> Jack |
| <input type="checkbox"/> Jack handle crank | <input type="checkbox"/> Card key | <input type="checkbox"/> Load cover |
| <input type="checkbox"/> Slow charging cable | <input type="checkbox"/> Locking wheel nuts key | <input type="checkbox"/> Refill tyre repair kit |
| <input type="checkbox"/> Charging cable bag | <input checked="" type="checkbox"/> Conformity certificate | <input checked="" type="checkbox"/> Registration certificate |
| <input checked="" type="checkbox"/> Spare Key | <input checked="" type="checkbox"/> Spare wheel tyre | <input type="checkbox"/> Satellite navigation |
| <input type="checkbox"/> Service book | <input type="checkbox"/> Quick charging cable | <input type="checkbox"/> In-car tools |
| <input type="checkbox"/> Towing hook | <input type="checkbox"/> Safety vest | <input type="checkbox"/> Locking wheel nut |
| <input type="checkbox"/> Cargo net | | |

Main set of tyres


| | | | |
|-------------|-------------|---------------------|------|
| Front Left | CONTINENTAL | 195 / 65 / 15 / All | 5 mm |
| Front Right | CONTINENTAL | 195 / 65 / 15 / All | 5 mm |
| Back Left | GOODYEAR | 195 / 65 / 15 / All | 4 mm |
| Back Right | GOODYEAR | 195 / 65 / 15 / All | 4 mm |

Comments

Pictures



Front left




Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation



Spare Tyre




Vin



Other



Other



Other



Dashboard trim / - / Punctured



Dashboard trim / - / Punctured



Gear lever console trim / - / Tear



Door interior trim / Front Left / Punctured




Door interior trim / Front Left / Punctured



Interior tailgate lining / Back Left / Broken



Interior tailgate lining / Back Left / Broken



Roof / - / Rust



Roof / - / Rust



Wheel hub cap / Front Left / Missing



Wheel hub cap / Front Left / Missing



Rear-view mirror / Left / Scratched




Rear-view mirror / Right / Broken



Rear-view mirror / Right / Broken



Rear-view mirror / Right / Broken



Bonnet / - / Dent




Bonnet / - / Dent




Bonnet / - / Dent




Bonnet / - / Dent



Bonnet / - / Dent



Headlight / Front Right / Scratched



Headlight / Front Right / Scratched



Bumper / Front / Broken



Bumper / Front / Broken



Bumper / Front / Broken



Headlight / Front Left / Scratched



Headlight / Front Left / Scratched



Wing / Front Left / Scratched



Wing / Front Left / Scratched



Wheel arch trim / Front Left / Broken



Wheel arch trim / Front Left / Broken



Door / Front Left / Dent



Door / Front Left / Dent



Door / Front Left / Dent



Doorframe seal / Front Left / Tear



Doorframe seal / Front Left / Tear



Door sill / Front Left / Scratched



Wing / Back Left / Dent




Wing / Back Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Rear light (wing) / Back Left / Broken



Rear light (wing) / Back Left / Broken



Rear light (wing) / Back Left / Broken



Fog lamp / Back Left / Broken



Fog lamp / Back Left / Broken



Bumper / Back / Broken



Bumper / Back / Broken



Bumper / Back / Broken



Door / Back Left / Scratched



Rear light (wing) / Back Right / Broken



Rear light (wing) / Back Right / Broken



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Sill / Right / Dent



Sill / Right / Dent



Sill / Right / Dent



Sill / Right / Dent



Sill / Right / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Door moulding / Right / Scratched



Door moulding / Right / Scratched



Door moulding / Front Right / Missing



Door / Front Right / Dent



Door / Front Right / Dent



Door / Front Right / Dent